

RADON TEST REPORT

BRODY MIDDLE SCHOOL
2502 PARK AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
112	2.2 ±	1	2014-02-04		2014-02-07		4651378	CONSULTANT	CC	
113	2.4 ±	1	2014-02-04		2014-02-07		4651375	CONSULTANT	CC	
116A	2.3 ±	1	2014-02-04		2014-02-07		4651374	CONSULTANT	CC	
119	2.7 ±	1	2014-02-04		2014-02-07		4651372	CONSULTANT	CC	
131	2.5 ±	1	2014-02-04		2014-02-07		4651369	CONSULTANT	CC	
143	2.2 ±	1	2014-02-04		2014-02-07		4651367	CONSULTANT	CC	
147	2.5 ±	1	2014-02-04		2014-02-07		4651368	CONSULTANT	CC	
151	1.2 ±	1	2014-02-04		2014-02-07		4651366	CONSULTANT	CC	
Cafeteria	2 ±	1	2014-02-04		2014-02-07		4651376	CONSULTANT	CC	
Counselor	3.8 ±	1	2014-02-04		2014-02-07		4738600	CONSULTANT	CC	
Gym	3.7 ±	1	2014-02-04		2014-02-07		4651371	CONSULTANT	CC	
Gym	3.3 ±	1	2014-02-04		2014-02-07		4651373	CONSULTANT	CC	
Library	2.6 ±	1	2014-02-04		2014-02-07		4651364	CONSULTANT	CC	
Library	2.5 ±	1	2014-02-04		2014-02-07		46541370	CONSULTANT	CC	
Work Room	1.9 ±	1	2014-02-04		2014-02-07		4651362	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

BRUBAKER ELEMENTARY
2900 E 42ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
114	0.6 ±	1	2014-01-22		2014-01-24		4633800	CONSULTANT	CC	
119	0.8 ±	1	2014-01-22		2014-01-24		4725385	CONSULTANT	CC	
126	0.7 ±	1	2014-01-22		2014-01-24		4633793	CONSULTANT	CC	
165	1.0 ±	1	2014-01-22		2014-01-24		4725372	CONSULTANT	CC	
173	1.5 ±	1	2014-01-22		2014-01-24		4633792	CONSULTANT	CC	
Cafeteria	<0.3 ±	1	2014-01-22		2014-01-24		4633798	CONSULTANT	CC	
Gym	1.0 ±	1	2014-01-22		2014-01-24		4633796	CONSULTANT	CC	
Library	1.2 ±	1	2014-01-22		2014-01-24		4725391	CONSULTANT	CC	
Main Office	0.5 ±	1	2014-01-22		2014-01-24		4725379	CONSULTANT	CC	
Music	0.9 ±	1	2014-01-22		2014-01-24		4725375	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CALLANAN MIDDLE SCHOOL
3010 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
001	\pm	0	2016-01-12	9:00 am			7701417	TYLER PULS	CC	2
002	1.9 \pm 0.4	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701419	TYLER PULS	CC	
003	< 0.3 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701421	TYLER PULS	CC	
005	1 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701422	TYLER PULS	CC	
005E	1 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701423	TYLER PULS	CC	
006	1.7 \pm 0.4	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701424	TYLER PULS	CC	
007	1.7 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701425	TYLER PULS	CC	
009	1.5 \pm 0.3	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701430	TYLER PULS	CC	
010A	1.6 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701426	TYLER PULS	CC	
010B	1.1 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701427	TYLER PULS	CC	
010C	1.3 \pm 0.3	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701428	TYLER PULS	CC	
011	1 \pm 0.3	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701431	TYLER PULS	CC	
011A	1.3 \pm 0.3	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701432	TYLER PULS	CC	
014	2.5 \pm 0.4	0	2016-01-12	10:00 am	2016-01-15	11:00 am	7701440	TYLER PULS	CC	
015	3.7 \pm 0.5	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701433	TYLER PULS	CC	
016	3.3 \pm 0.5	0	2016-01-12	10:00 am	2016-01-15	10:00 am	7701434	TYLER PULS	CC	
019	1.1 \pm 0.3	0	2016-01-12	9:00 am	2016-01-15	10:00 am	7701418	TYLER PULS	CC	
101A	0.7 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701447	TYLER PULS	CC	
104	0.8 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701446	TYLER PULS	CC	
105	0.8 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701445	TYLER PULS	CC	
106	1 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701444	TYLER PULS	CC	
107	0.9 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701443	TYLER PULS	CC	
110	0.7 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701442	TYLER PULS	CC	
113	0.6 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701438	TYLER PULS	CC	
114	< 0.3 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701437	TYLER PULS	CC	
115	< 0.3 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	10:00 am	7701436	TYLER PULS	CC	
116	< 0.3 \pm 0.3	1	2016-01-12	10:00 am	2016-01-15	10:00 am	7701435	TYLER PULS	CC	
118	2.7 \pm 0.4	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701439	TYLER PULS	CC	
119	3.2 \pm 0.5	1	2016-01-12	10:00 am	2016-01-15	11:00 am	7701441	TYLER PULS	CC	
121	0.9 \pm 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701448	TYLER PULS	CC	
122	0.9 \pm 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701451	TYLER PULS	CC	
123	1 \pm 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701449	TYLER PULS	CC	

RADON TEST REPORT

CALLANAN MIDDLE SCHOOL
3010 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
124	0.6 ± 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701453	TYLER PULS	CC	
125	±	1	2016-01-12	11:00 am			7701454	TYLER PULS	CC	2
126	0.9 ± 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701455	TYLER PULS	CC	
127	0.8 ± 0.3	1	2016-01-12	11:00 am	2016-01-15	11:00 am	7701456	TYLER PULS	CC	
200N	0.7 ± 0.3	2	2016-01-12	11:00 am	2016-01-15	11:00 am	7701458	TYLER PULS	CC	
211	0.7 ± 0.3	2	2016-01-12	11:00 am	2016-01-15	11:00 am	7701459	TYLER PULS	CC	
1	5.3 ±	1	2013-03-21		2013-06-27		4894927	CONSULTANT	AT	
19	6.7 ±	1	2013-03-21		2013-06-27		4894902	CONSULTANT	AT	
9	7.1 ±	1	2013-03-21		2013-06-27		4894912	CONSULTANT	AT	
Auditorium	5.5 ±	1	2013-03-21		2013-06-27		4894896	CONSULTANT	AT	
2	3.5 ±	1	2013-02-14		2013-02-07		4464350	CONSULTANT	CC	
Auditorium	5.8 ±	1	2013-02-13		2013-02-07		4464339	CONSULTANT	CC	
Gym North	2.1 ±	1	2013-02-12		2013-02-07		4464341	CONSULTANT	CC	
19	5.8 ±	1	2013-02-11		2013-02-07		4464353	CONSULTANT	CC	
1	4.8 ±	1	2013-02-10		2013-02-07		4464340	CONSULTANT	CC	
3	2.6 ±	1	2013-02-09		2013-02-07		4464352	CONSULTANT	CC	
5	2.1 ±	1	2013-02-08		2013-02-07		4464355	CONSULTANT	CC	
10A	3.8 ±	1	2013-02-07		2013-02-07		4464354	CONSULTANT	CC	
6	3.1 ±	1	2013-02-06		2013-02-07		4464336	CONSULTANT	CC	
7	3.5 ±	1	2013-02-05		2013-02-07		4464335	CONSULTANT	CC	
9	4 ±	1	2013-02-04		2013-02-07		4464351	CONSULTANT	CC	

RADON TEST REPORT

CALLANAN MIDDLE SCHOOL
3010 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CAPITAL VIEW ELEMENTARY
330 E 16TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
126	1.2 ± 0.3	1	2016-03-21	12:00 pm	2016-03-25	12:00 pm	7701936	TYLER PULS	CC	
128	1.7 ± 0.4	1	2016-03-21	12:00 pm	2016-03-25	12:00 pm	7701934	TYLER PULS	CC	
135	1.5 ± 0.4	1	2016-03-21	12:00 pm	2016-03-25	12:00 pm	7701933	TYLER PULS	CC	
103	1 ±	1	2014-01-27		2014-01-30		4651503	CONSULTANT	CC	
120	0.7 ±	1	2014-01-27		2014-01-30		4651508	CONSULTANT	CC	
126	0.6 ±	1	2014-01-27		2014-01-30		4651509	CONSULTANT	CC	
128	1.1 ±	1	2014-01-27		2014-01-30		4651510	CONSULTANT	CC	
135	1.3 ±	1	2014-01-27		2014-01-30		4651506	CONSULTANT	CC	
136	0.9 ±	1	2014-01-27		2014-01-30		4651501	CONSULTANT	CC	
153	1.5 ±	1	2014-01-27		2014-01-30		4651507	CONSULTANT	CC	
Gym	0.9 ±	1	2014-01-27		2014-01-30		4651502	CONSULTANT	CC	
Library	1 ±	1	2014-01-27		2014-01-30		4651504	CONSULTANT	CC	
124	0.7 ±	1	2011-11-07		2011-11-10		4448647	CONSULTANT	CC	
126	0.9 ±	1	2011-11-07		2011-11-10		4448643	CONSULTANT	CC	
128	0.7 ±	1	2011-11-07		2011-11-10		4448646	CONSULTANT	CC	
Gym	0.8 ±	1	2011-11-07		2011-11-10		4448645	CONSULTANT	CC	
Gym	0.8 ±	1	2011-11-07		2011-11-10		4448638	CONSULTANT	CC	
Nurse	0.8 ±	1	2011-11-07		2011-11-10		4448640	CONSULTANT	CC	

RADON TEST REPORT

CAPITAL VIEW ELEMENTARY
320 E 16TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CARVER ELEMENTARY
705 E UNIVERSITY



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1014	1.5 ±	1	2014-03-10		2014-03-13		4651480	CONSULTANT	CC	
1034	1.1 ±	1	2014-03-10		2014-03-13		4651482	CONSULTANT	CC	
1042	1.1 ±	1	2014-03-10		2014-03-13		4651474	CONSULTANT	CC	
1043	1.3 ±	1	2014-03-10		2014-03-13		4651481	CONSULTANT	CC	
1046	1.2 ±	1	2014-03-10		2014-03-13		4651478	CONSULTANT	CC	
1049	1.3 ±	1	2014-03-10		2014-03-13		4651476	CONSULTANT	CC	
2063	1.0 ±	1	2014-03-10		2014-03-13		4651485	CONSULTANT	CC	
2064	1.1 ±	2	2014-03-10		2014-03-13		4651479	CONSULTANT	CC	
Gym	1.8 ±	1	2014-03-10		2014-03-13		4651475	CONSULTANT	CC	
Gym	1.8 ±	2	2014-03-10		2014-03-13		4651484	CONSULTANT	CC	
Library	1.2 ±	1	2014-03-10		2014-03-13		4651483	CONSULTANT	CC	
2063	0.6 ±	2	2012-03-07		2012-03-09		4542252	CONSULTANT	CC	
2064	0.9 ±	2	2012-03-07		2012-03-09		4542248	CONSULTANT	CC	
1049	1.2 ±	1	2011-11-07		2011-11-10		4448634	CONSULTANT	CC	
1142	1.1 ±	1	2011-11-07		2011-11-10		4448633	CONSULTANT	CC	
1143	1.5 ±	1	2011-11-07		2011-11-10		4448619	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CATTELL ELEMENTARY
3101 E 16TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
6	1.1 ±	1	2014-03-05		2014-07-25		4937622	CONSULTANT	AT	
8	1.3 ±	1	2014-03-05		2014-07-25		4937666	CONSULTANT	AT	
1	3.1 ±	1	2014-02-11		2014-02-14		4651409	CONSULTANT	CC	
105	3.2 ±	1	2014-02-11		2014-02-14		4651406	CONSULTANT	CC	
117	2.0 ±	1	2014-02-11		2014-02-14		4651408	CONSULTANT	CC	
118	2.0 ±	1	2014-02-11		2014-02-14		4651414	CONSULTANT	CC	
119	1.4 ±	1	2014-02-11		2014-02-14		4651411	CONSULTANT	CC	
2	3.0 ±	1	2014-02-11		2014-02-14		4651410	CONSULTANT	CC	
6	4.5 ±	1	2014-02-11		2014-02-14		4651407	CONSULTANT	CC	
8	5.0 ±	1	2014-02-11		2014-02-14		4651412	CONSULTANT	CC	
Gym	1.9 ±	1	2014-02-11		2014-02-14		4651416	CONSULTANT	CC	
Gym	2.3 ±	1	2014-02-11		2014-02-14		4651415	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CENTRAL ACADEMY
1912 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1000	1.3 ±	1	2014-02-04		2014-02-07		4651394	CONSULTANT	CC	
1005	1.6 ±	1	2014-02-04		2014-02-07		4651602	CONSULTANT	CC	
1006	2.5 ±	1	2014-02-04		2014-02-07		4651388	CONSULTANT	CC	
1007	2.1 ±	1	2014-02-04		2014-02-07		4651606	CONSULTANT	CC	
1013	1.2 ±	1	2014-02-04		2014-02-07		4651389	CONSULTANT	CC	
1014	0.9 ±	1	2014-02-04		2014-02-07		4651396	CONSULTANT	CC	
1016	1.1 ±	1	2014-02-04		2014-02-07		4651390	CONSULTANT	CC	
1021	1.2 ±	1	2014-02-04		2014-02-07		4651387	CONSULTANT	CC	
1022	1.4 ±	1	2014-02-04		2014-02-07		4651381	CONSULTANT	CC	
1023	1.2 ±	1	2014-02-04		2014-02-07		4651383	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

CENTRAL CAMPUS
1800 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
13	<0.3 ±	1	2014-02-04		2014-02-07		4651400	CONSULTANT	CC	
15	<0.3 ±	1	2014-02-04		2014-02-07		4651395	CONSULTANT	CC	
16	<0.3 ±	1	2014-02-04		2014-02-07		4651397	CONSULTANT	CC	
1606	0.7 ±	2	2014-02-04		2014-02-07		4651607	CONSULTANT	CC	
1608	0.7 ±	2	2014-02-04		2014-02-07		4651608	CONSULTANT	CC	
18F	<0.3 ±	1	2014-02-04		2014-02-07		4651610	CONSULTANT	CC	
19	0.5 ±	1	2014-02-04		2014-02-07		4651604	CONSULTANT	CC	
19	<0.3 ±	1	2014-02-04		2014-02-07		4651603	CONSULTANT	CC	
21	<0.3 ±	1	2014-02-04		2014-02-07		4651609	CONSULTANT	CC	
7000	0.6 ±	1	2014-02-04		2014-02-07		4651399	CONSULTANT	CC	
Lower Gym	3.3 ±	1	2014-02-04		2014-02-07		4651611	CONSULTANT	CC	
Pool	1.3 ±	1	2014-02-04		2014-02-07		4651601	CONSULTANT	CC	
Pool	1.6 ±	1	2014-02-04		2014-02-07		4651398	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

COWLES ELEMENTARY
6401 COLLEGE AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
107	7.6 ± 0.8	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701939	TYLER PULS	CC	
108	6.8 ± 0.8	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701941	TYLER PULS	CC	
109	7.2 ± 0.8	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701943	TYLER PULS	CC	
110	8.4 ± 0.9	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701945	TYLER PULS	CC	
111	7.5 ± 0.8	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701942	TYLER PULS	CC	
112	8 ± 0.9	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701940	TYLER PULS	CC	
119	1 ± 0.3	1	2016-03-21	2:00 pm	2016-03-25	1:00 pm	7701947	TYLER PULS	CC	
110	5.7 ±	1	2016-02-16	10:13	2016-02-19	10:13		TYLER PULS	CRM	
110	5.6 ± 0.5	1	2016-02-16	1:00 pm	2016-02-19	12:00 pm	7701900	TYLER PULS	CC	
110	2.7 ±	1	2014-04-28		2014-04-30			CONSULTANT	CRM	
107	2.3 ±	1	2014-03-03		2014-07-25		4937561	CONSULTANT	AT	
109	2.5 ±	1	2014-03-03		2014-07-25		4937611	CONSULTANT	AT	
110	8.4 ±	1	2014-03-03		2014-03-06		4651437	CONSULTANT	CC	
111	3.7 ±	1	2014-03-03		2014-07-25		4937624	CONSULTANT	AT	
105	2.3 ±	1	2014-02-10		2014-02-13		4651656	CONSULTANT	CC	
106	3.4 ±	1	2014-02-10		2014-02-13		4651657	CONSULTANT	CC	
107	5.8 ±	1	2014-02-10		2014-02-13		4651661	CONSULTANT	CC	
109	5.4 ±	1	2014-02-10		2014-02-13		4651660	CONSULTANT	CC	
110	8.8 ±	1	2014-02-10		2014-02-13		4651658	CONSULTANT	CC	
111	7.3 ±	1	2014-02-10		2014-02-13		4651655	CONSULTANT	CC	
112	3.4 ±	1	2014-02-10		2014-02-13		4651654	CONSULTANT	CC	
119	1.5 ±	1	2014-02-10		2014-02-13		4651653	CONSULTANT	CC	
121	1 ±	1	2014-02-10		2014-02-13		4651651	CONSULTANT	CC	
Gym	1.1 ±	1	2014-02-10		2014-02-13		4651652	CONSULTANT	CC	
105	2.5 ±	1	2013-01-09		2013-01-11		4464325	CONSULTANT	CC	
106	3.3 ±	1	2013-01-09		2013-01-11		4464324	CONSULTANT	CC	
109	3.4 ±	1	2013-01-09		2013-01-11		4464326	CONSULTANT	CC	
110	8.4 ±	1	2013-01-09		2013-01-11		4464317	CONSULTANT	CC	
111	4.2 ±	1	2013-01-09		2013-01-11		4464322	CONSULTANT	CC	
112	3.6 ±	1	2013-01-09		2013-01-11		4464320	CONSULTANT	CC	
105	4 ±	1	2012-09-26		2012-09-28		4464311	CONSULTANT	CC	
106	5 ±	1	2012-09-26		2012-09-28		4464306	CONSULTANT	CC	

RADON TEST REPORT

COWLES ELEMENTARY
6401 COLLEGE AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
109	4 ±	1	2012-09-26		2012-09-28		4464313	CONSULTANT	CC	
110	5.6 ±	1	2012-09-26		2012-09-28		4464314	CONSULTANT	CC	
111	4.3 ±	1	2012-09-26		2012-09-28		4464312	CONSULTANT	CC	
112	2.6 ±	1	2012-09-26		2012-09-28		4464315	CONSULTANT	CC	
105	7.2 ±	1	2012-03-30		2012-07-16		4858507	CONSULTANT	AT	
106	9.8 ±	1	2012-03-30		2012-07-16		4858502	CONSULTANT	AT	
109	11.5 ±	1	2012-03-30		2012-07-16		4858468	CONSULTANT	AT	
110	11.3 ±	1	2012-03-30		2012-07-16		4858454	CONSULTANT	AT	
111	9.3 ±	1	2012-03-30		2012-07-16		4858457	CONSULTANT	AT	
112	6.7 ±	1	2012-03-30		2012-07-16		4858515	CONSULTANT	AT	
1	3.4 ±	1	2012-03-07		2012-03-09		4542241	CONSULTANT	CC	
105	8.7 ±	1	2012-03-07		2012-03-09		4542240	CONSULTANT	CC	
106	11 ±	1	2012-03-07		2012-03-09		4542246	CONSULTANT	CC	
109	12.5 ±	1	2012-03-07		2012-03-09		4542244	CONSULTANT	CC	
110	10.8 ±	1	2012-03-07		2012-03-09		4542247	CONSULTANT	CC	
111	11.1 ±	1	2012-03-07		2012-03-09		4542245	CONSULTANT	CC	
112	10.4 ±	1	2012-03-07		2012-03-09		4542239	CONSULTANT	CC	
Gym NE	2.4 ±	1	2012-03-07		2012-03-09		4542242	CONSULTANT	CC	
Gym NW	2.2 ±	1	2012-03-07		2012-03-09		4542243	CONSULTANT	CC	
Library	3.8 ±	1	2012-03-07		2012-03-09		4542226	CONSULTANT	CC	

RADON TEST REPORT

COWLES ELEMENTARY
6401 COLLEGE AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

DOWNTOWN SCHOOL
1800 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1001	<0.3 ±	1	2014-01-27		2014-01-30		4651518	CONSULTANT	CC	
1010	<0.3 ±	1	2014-01-27		2014-01-30		4651526	CONSULTANT	CC	
1101	<0.3 ±	1	2014-01-27		2014-01-30		4651527	CONSULTANT	CC	
1103	<0.3 ±	1	2014-01-27		2014-01-30		4651530	CONSULTANT	CC	
1105	0.6 ±	1	2014-01-27		2014-01-30		4651517	CONSULTANT	CC	
1107	<0.3 ±	1	2014-01-27		2014-01-30		4651533	CONSULTANT	CC	
1301	0.6 ±	1	2014-01-27		2014-01-30		4651519	CONSULTANT	CC	
1303	<0.3 ±	1	2014-01-27		2014-01-30		4651536	CONSULTANT	CC	
1325	<0.3 ±	1	2014-01-27		2014-01-30		4651535	CONSULTANT	CC	
Library	<0.3 ±	1	2014-01-27		2014-01-30		4651531	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

EAST HIGH SCHOOL
815 E 13TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1022	0.8 ±	1	2014-01-28		2014-01-31		4651556	CONSULTANT	CC	
1028	1.0 ±	1	2014-01-28		2014-01-31		4651544	CONSULTANT	CC	
1045	1.3 ±	1	2014-01-28		2014-01-31		4651555	CONSULTANT	CC	
1047	2.1 ±	1	2014-01-28		2014-01-31		4651550	CONSULTANT	CC	
1054	1.6 ±	1	2014-01-28		2014-01-31		4651539	CONSULTANT	CC	
1060	1.7 ±	1	2014-01-28		2014-01-31		4651537	CONSULTANT	CC	
1061	1.6 ±	1	2014-01-28		2014-01-31		4651522	CONSULTANT	CC	
1065	2.0 ±	1	2014-01-28		2014-01-31		4651551	CONSULTANT	CC	
1069	1.5 ±	1	2014-01-28		2014-01-31		4651547	CONSULTANT	CC	
1070	0.9 ±	1	2014-01-28		2014-01-31		4651546	CONSULTANT	CC	
1074	1.2 ±	1	2014-01-28		2014-01-31		4651540	CONSULTANT	CC	
1077	1.3 ±	1	2014-01-28		2014-01-31		4651545	CONSULTANT	CC	
1079	2.0 ±	1	2014-01-28		2014-01-31		4651554	CONSULTANT	CC	
1081	2.0 ±	1	2014-01-28		2014-01-31		4651553	CONSULTANT	CC	
42	<0.3 ±	0	2014-01-28		2014-01-31		4651543	CONSULTANT	CC	
47	1.8 ±	0	2014-01-28		2014-01-31		4651541	CONSULTANT	CC	
93	1.0 ±	0	2014-01-28		2014-01-31		4651523	CONSULTANT	CC	
Library	1.2 ±	1	2014-01-28		2014-01-31		4651548	CONSULTANT	CC	
Main Office	0.7 ±	1	2014-01-28		2014-01-31		4651552	CONSULTANT	CC	
Nurse	1.0 ±	1	2014-01-28		2014-01-31		4651538	CONSULTANT	CC	

RADON TEST REPORT

EAST HIGH SCHOOL
815 E 13TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

EDMUNDS ELEMENTARY
915 15TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1200	1.0 ±	1	2014-03-10		2014-03-13		4651486	CONSULTANT	CC	
1205	0.8 ±	1	2014-03-10		2014-03-13		4651495	CONSULTANT	CC	
1210	1.7 ±	1	2014-03-10		2014-03-13		4651489	CONSULTANT	CC	
1230	1.0 ±	1	2014-03-10		2014-03-13		4651493	CONSULTANT	CC	
1250	1.1 ±	1	2014-03-10		2014-03-13		4651490	CONSULTANT	CC	
1265	1.3 ±	1	2014-03-10		2014-03-13		4651494	CONSULTANT	CC	
1430	1.2 ±	1	2014-03-10		2014-03-13		4651491	CONSULTANT	CC	
Cafeteria	1.2 ±	1	2014-03-10		2014-03-13		4651487	CONSULTANT	CC	
Gym	1.4 ±	1	2014-03-10		2014-03-13		4651492	CONSULTANT	CC	
Gym	1.3 ±	1	2014-03-10		2014-03-13		4651488	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

FINDLEY ELEMENTARY
3025 OXFORD STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1203	3.4 ±	1	2014-04-16		2014-07-34		4937696	CONSULTANT	AT	
1206	4.2 ±	1	2014-04-15		2014-07-33		4937617	CONSULTANT	AT	
1316	3.4 ±	1	2014-04-14		2014-07-32		4937566	CONSULTANT	AT	
1324	2.7 ±	1	2014-04-13		2014-07-31		4937589	CONSULTANT	AT	
1319	3.2 ±	1	2014-04-12		2014-07-30		4937585	CONSULTANT	AT	
1334	2.9 ±	1	2014-04-11		2014-07-29		4937582	CONSULTANT	AT	
Cafeteria	3.6 ±	1	2014-04-09		2014-07-27		4937619	CONSULTANT	AT	
1217	3.4 ±	1	2014-04-08		2014-07-26		4937571	CONSULTANT	AT	
1008	3.4 ±	1	2014-04-07		2014-07-25		4937658	CONSULTANT	AT	
1008	4.6 ±	1	2014-03-24		2014-03-27		4651207	CONSULTANT	CC	
1203	5.0 ±	1	2014-03-24		2014-03-27		4651203	CONSULTANT	CC	
1206	7.5 ±	1	2014-03-24		2014-03-27		4738595	CONSULTANT	CC	
1217	5.7 ±	1	2014-03-24		2014-03-27		4651202	CONSULTANT	CC	
1316	4.8 ±	1	2014-03-24		2014-03-27		4738597	CONSULTANT	CC	
1319	4.4 ±	1	2014-03-24		2014-03-27		4738596	CONSULTANT	CC	
1324	4.0 ±	1	2014-03-24		2014-03-27		4738592	CONSULTANT	CC	
1334	4.8 ±	1	2014-03-24		2014-03-27		4738594	CONSULTANT	CC	
Cafeteria	5.1 ±	1	2014-03-24		2014-03-27		4738591	CONSULTANT	CC	
Cafeteria	5.8 ±	1	2014-03-24		2014-03-27		4738588	CONSULTANT	CC	
101	2.7 ±	1	2011-11-07		2011-11-10		4448623	CONSULTANT	CC	
102	2.1 ±	1	2011-11-07		2011-11-10		4448612	CONSULTANT	CC	

RADON TEST REPORT

FINDLEY ELEMENTARY
3025 OXFORD STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

GARTON ELEMENTARY
2820 E 24TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
Main Office	5.7 ±	1	2014-02-06		2014-07-25		4924345	CONSULTANT	AT	
145	2.5 ±	1	2014-02-04		2014-07-25		4924341	CONSULTANT	AT	
114	2.5 ±	1	2014-01-22		2014-01-24		4633795	CONSULTANT	CC	
122	1.9 ±	1	2014-01-22		2014-01-24		4633799	CONSULTANT	CC	
130	1.6 ±	1	2014-01-22		2014-01-24		4633794	CONSULTANT	CC	
133	0.8 ±	1	2014-01-22		2014-01-24		4725382	CONSULTANT	CC	
136	0.6 ±	1	2014-01-22		2014-01-24		4633786	CONSULTANT	CC	
141	2.1 ±	1	2014-01-22		2014-01-24		4725377	CONSULTANT	CC	
145	9.3 ±	1	2014-01-22		2014-01-24		4725381	CONSULTANT	CC	
152	2.3 ±	1	2014-01-22		2014-01-24		4725371	CONSULTANT	CC	
Library	1.2 ±	1	2014-01-22		2014-01-24		4725374	CONSULTANT	CC	
Main Office	4.6 ±	1	2014-01-22		2014-01-24		4725394	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

GOODRELL MIDDLE SCHOOL
3300 E 29TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1002	1.6 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701550	TYLER PULS	CC	
1004	1.5 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701549	TYLER PULS	CC	
1005	1.9 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701548	TYLER PULS	CC	
1006	1.5 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701546	TYLER PULS	CC	
1008	1.5 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701544	TYLER PULS	CC	
1009	1.4 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701545	TYLER PULS	CC	
1015	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701541	TYLER PULS	CC	
1016	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701542	TYLER PULS	CC	
1017	1.4 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	11:00 am	7701543	TYLER PULS	CC	
1018	2.2 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701552	TYLER PULS	CC	
1019	2.8 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701554	TYLER PULS	CC	
1020	1.9 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701537	TYLER PULS	CC	
1021	1.9 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701536	TYLER PULS	CC	
1022	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701539	TYLER PULS	CC	
1023	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701533	TYLER PULS	CC	
1024	1.8 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701538	TYLER PULS	CC	
1025	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701534	TYLER PULS	CC	
1026	2 ± 0.4	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701535	TYLER PULS	CC	
1029	1.3 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701585	TYLER PULS	CC	
1031	1.5 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701587	TYLER PULS	CC	
1032	1.3 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701586	TYLER PULS	CC	
1033	1.7 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701583	TYLER PULS	CC	
1034	1.1 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701589	TYLER PULS	CC	
1046	2.3 ± 0.4	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701582	TYLER PULS	CC	
1048	1.8 ± 0.3	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701581	TYLER PULS	CC	
1053	1.4 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	11:00 am	7701578	TYLER PULS	CC	
1053A	1.5 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	11:00 am	7701579	TYLER PULS	CC	
1054	1.4 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	11:00 am	7701580	TYLER PULS	CC	
1059	1.2 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701575	TYLER PULS	CC	
1061	1 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701576	TYLER PULS	CC	
1063	2.3 ± 0.4	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701594	TYLER PULS	CC	
1065	1.9 ± 0.4	1	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701593	TYLER PULS	CC	

RADON TEST REPORT

GOODRELL MIDDLE SCHOOL
3300 E 29TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1066	1 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701577	TYLER PULS	CC	
1067	2 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701557	TYLER PULS	CC	
1070	1.3 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701555	TYLER PULS	CC	
1071	1.7 ± 0.3	1	2016-01-25	10:00 am	2016-01-29	10:00 am	7701551	TYLER PULS	CC	
1072	2.6 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701561	TYLER PULS	CC	
1073	2.3 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701559	TYLER PULS	CC	
1074	0.8 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701558	TYLER PULS	CC	
1080	1.1 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701574	TYLER PULS	CC	
1082	1.3 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701563	TYLER PULS	CC	
1083	0.9 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701564	TYLER PULS	CC	
1085	1.3 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701565	TYLER PULS	CC	
1086	2.1 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701569	TYLER PULS	CC	
1087	1.8 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701568	TYLER PULS	CC	
1088	1.5 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701567	TYLER PULS	CC	
1089	2.2 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701571	TYLER PULS	CC	
1090	2.7 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701570	TYLER PULS	CC	
1150	2.4 ± 0.4	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701573	TYLER PULS	CC	2
1174	1 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701556	TYLER PULS	CC	
1175	1 ± 0.3	1	2016-01-25	11:00 am	2016-01-29	10:00 am	7701562	TYLER PULS	CC	
2005	0.7 ± 0.3	2	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701592	TYLER PULS	CC	
2027	1.6 ± 0.3	2	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701590	TYLER PULS	CC	
2063	1.2 ± 0.3	2	2016-01-25	12:00 pm	2016-01-29	11:00 am	7701591	TYLER PULS	CC	

RADON TEST REPORT

GOODRELL MIDDLE SCHOOL
3300 E 29TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

GREENWOOD ELEMENTARY
316 37TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
24	3.8 ±	1	2013-03-24		2013-06-30		4894907	CONSULTANT	AT	
108	4.1 ±	1	2013-03-23		2013-06-29		4894913	CONSULTANT	AT	
129	3.1 ±	1	2013-03-22		2013-06-28		4894937	CONSULTANT	AT	
117	2.8 ±	1	2013-03-21		2013-06-27		4894897	CONSULTANT	AT	
104	3.5 ±	1	2013-02-04		2013-02-07		4464321	CONSULTANT	CC	
107	2 ±	1	2013-02-04		2013-02-07		4464342	CONSULTANT	CC	
108	5.2 ±	1	2013-02-04		2013-02-07		4464330	CONSULTANT	CC	
109	2.6 ±	1	2013-02-04		2013-02-07		4464329	CONSULTANT	CC	
110	1.4 ±	1	2013-02-04		2013-02-07		4464346	CONSULTANT	CC	
113	1.2 ±	1	2013-02-04		2013-02-07		4464308	CONSULTANT	CC	
114	1.4 ±	1	2013-02-04		2013-02-07		4464328	CONSULTANT	CC	
115	1.3 ±	1	2013-02-04		2013-02-07		4464347	CONSULTANT	CC	
116	1.3 ±	1	2013-02-04		2013-02-07		4464333	CONSULTANT	CC	
117	4.2 ±	1	2013-02-04		2013-02-07		4464345	CONSULTANT	CC	
12	3.7 ±	0	2013-02-04		2013-02-07		4464344	CONSULTANT	CC	
129	4.1 ±	1	2013-02-04		2013-02-07		4464343	CONSULTANT	CC	
17	3.5 ±	0	2013-02-04		2013-02-07		4464348	CONSULTANT	CC	
24	5.7 ±	0	2013-02-04		2013-02-07		4464349	CONSULTANT	CC	
Gym	3.8 ±	0	2013-02-04		2013-02-07		4464337	CONSULTANT	CC	
Office	3.7 ±	1	2013-02-04		2013-02-07		4464338	CONSULTANT	CC	

RADON TEST REPORT

GREENWOOD ELEMENTARY
316 37TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HANAWALT ELEMENTARY
225 56TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
113	5.3 ±	1	2016-02-09	8:42	2016-02-12	8:42		TYLER PULS	CRM	
114	6.0 ±	1	2016-02-03	10:35	2016-02-06	10:35		TYLER PULS	CRM	
100	3 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701351	TYLER PULS	CC	
101	2.8 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701352	TYLER PULS	CC	
102	3.4 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701353	TYLER PULS	CC	
103	4.1 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701411	TYLER PULS	CC	
103A	3.7 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701412	TYLER PULS	CC	
105	3.5 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701409	TYLER PULS	CC	
105A	3.7 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701410	TYLER PULS	CC	
106	4 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701354	TYLER PULS	CC	
107	3.2 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701356	TYLER PULS	CC	
108	4.5 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701357	TYLER PULS	CC	
108A	4.8 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701358	TYLER PULS	CC	
108B	4.5 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701364	TYLER PULS	CC	
109	3.2 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701359	TYLER PULS	CC	
110	3.9 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701360	TYLER PULS	CC	
111	5.2 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701362	TYLER PULS	CC	
112	5.7 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701363	TYLER PULS	CC	
113	6.5 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701365	TYLER PULS	CC	
114	8.2 ± 0.5	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701366	TYLER PULS	CC	
115	7.2 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701367	TYLER PULS	CC	
116	6.4 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701401	TYLER PULS	CC	
117	6 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701402	TYLER PULS	CC	
118	5 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701404	TYLER PULS	CC	
119	6 ± 0.4	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701403	TYLER PULS	CC	
120	4.3 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701405	TYLER PULS	CC	
121	4.2 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701406	TYLER PULS	CC	
122	3.6 ± 0.3	1	2015-12-15	11:00 am	2015-12-18	12:00 pm	7701407	TYLER PULS	CC	
123	2.2 ± 0.3	1	2015-12-15	12:00 pm	2015-12-18	12:00 pm	7701413	TYLER PULS	CC	
125	3.6 ± 0.3	1	2015-12-15	12:00 pm	2015-12-18	12:00 pm	7701415	TYLER PULS	CC	
201	1.8 ± 0.3	2	2015-12-15	12:00 pm	2015-12-18	12:00 pm	7701416	TYLER PULS	CC	
110	5.6 ±	1	2013-03-21		2013-06-27		4894926	CONSULTANT	AT	

RADON TEST REPORT

HANAWALT ELEMENTARY
225 56TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
125	4.8 ±	0	2013-03-21		2013-06-27		4894898	CONSULTANT	AT	
Cafeteria	4.7 ±	1	2013-03-21		2013-06-27		4894919	CONSULTANT	AT	
Gym	5.5 ±	1	2013-03-21		2013-06-27		4894879	CONSULTANT	AT	
100	2.9 ±	1	2013-02-19		2013-02-22		4600205	CONSULTANT	CC	
108	2.3 ±	1	2013-02-19		2013-02-22		4600203	CONSULTANT	CC	
109	3.5 ±	1	2013-02-19		2013-02-22		4600198	CONSULTANT	CC	
110	4.7 ±	1	2013-02-19		2013-02-22		4600199	CONSULTANT	CC	
112	2.5 ±	1	2013-02-19		2013-02-22		4600201	CONSULTANT	CC	
114	3.7 ±	1	2013-02-19		2013-02-22		4600188	CONSULTANT	CC	
116	2.7 ±	1	2013-02-19		2013-02-22		4600204	CONSULTANT	CC	
118	3.3 ±	1	2013-02-19		2013-02-22		4600162	CONSULTANT	CC	
120	2.7 ±	1	2013-02-19		2013-02-22		4600206	CONSULTANT	CC	
122	2.8 ±	1	2013-02-19		2013-02-22		4600178	CONSULTANT	CC	
123	3.3 ±	0	2013-02-19		2013-02-22		4600211	CONSULTANT	CC	
125	4.4 ±	0	2013-02-19		2013-02-22		4600213	CONSULTANT	CC	
Cafeteria	4.1 ±	1	2013-02-19		2013-02-22		4600212	CONSULTANT	CC	
Gym	5.4 ±	1	2013-02-19		2013-02-22		4600214	CONSULTANT	CC	

RADON TEST REPORT

HANAWALT ELEMENTARY
225 56TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HARDING MIDDLE SCHOOL
203 E EUCLID AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
151	5.0 \pm	1	2013-03-22		2013-06-27		4894908	CONSULTANT	AT	
48	8.0 \pm	0	2013-03-22		2013-06-27		4894887	CONSULTANT	AT	
48C	8.0 \pm	0	2013-03-22		2013-06-27		4894916	CONSULTANT	AT	
105	1.0 \pm	1	2013-02-19		2013-02-21		4600165	CONSULTANT	CC	
111	1.4 \pm	1	2013-02-19		2013-02-21		4600167	CONSULTANT	CC	
128	3.0 \pm	1	2013-02-19		2013-02-21		4600163	CONSULTANT	CC	
129	2.3 \pm	1	2013-02-19		2013-02-21		4600174	CONSULTANT	CC	
151	7.1 \pm	1	2013-02-19		2013-02-21		4600155	CONSULTANT	CC	
42	0.8 \pm	0	2013-02-19		2013-02-21		4600161	CONSULTANT	CC	
46	0.5 \pm	0	2013-02-19		2013-02-21		4600168	CONSULTANT	CC	
48	6.2 \pm	0	2013-02-19		2013-02-21		4600170	CONSULTANT	CC	
48C	7.1 \pm	0	2013-02-19		2013-02-21		4600171	CONSULTANT	CC	
54	0.8 \pm	0	2013-02-19		2013-02-21		4600169	CONSULTANT	CC	
Auditorium	3.8 \pm	1	2013-02-19		2013-02-21		4600157	CONSULTANT	CC	
Computer Ro	2.4 \pm	1	2013-02-19		2013-02-21		4600164	CONSULTANT	CC	
Main Office	2.4 \pm	1	2013-02-19		2013-02-21		4600159	CONSULTANT	CC	
Media Cente	1.5 \pm	1	2013-02-19		2013-02-21		4600156	CONSULTANT	CC	
Music Room	1.9 \pm	1	2013-02-19		2013-02-21		4600158	CONSULTANT	CC	

RADON TEST REPORT

HARDING MIDDLE SCHOOL
203 E EUCLID AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HIATT MIDDLE SCHOOL
1430 E UNIVERSITY AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1000	1.8 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701701	TYLER PULS	CC	
1030	1.7 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701700	TYLER PULS	CC	
1070	2 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701710	TYLER PULS	CC	
1085	2.1 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701711	TYLER PULS	CC	
1090	2.2 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701704	TYLER PULS	CC	
1095	1.7 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701705	TYLER PULS	CC	
1110	1.8 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701703	TYLER PULS	CC	
1115	1.5 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701707	TYLER PULS	CC	
1120	1.9 ± 0.4	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701709	TYLER PULS	CC	
1135	1.6 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701702	TYLER PULS	CC	
1200	1.7 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701687	TYLER PULS	CC	
1210	2 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701688	TYLER PULS	CC	
1215	1.8 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701689	TYLER PULS	CC	
1225	2.2 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701690	TYLER PULS	CC	2
1230	1.9 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701691	TYLER PULS	CC	
1240	2.3 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701692	TYLER PULS	CC	
1245	2.1 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701693	TYLER PULS	CC	
1270	< 0.3 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701694	TYLER PULS	CC	
1270A	0.7 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701695	TYLER PULS	CC	
1280	1.1 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701696	TYLER PULS	CC	
1320	0.7 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701697	TYLER PULS	CC	
1325	< 0.3 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701698	TYLER PULS	CC	
1400	1.6 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701686	TYLER PULS	CC	
1405	1.8 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701685	TYLER PULS	CC	
1415	3.5 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701683	TYLER PULS	CC	
1420	4.4 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701682	TYLER PULS	CC	
1435	1.8 ± 0.3	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701681	TYLER PULS	CC	
1440	2.5 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701680	TYLER PULS	CC	
1500	4.6 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701674	TYLER PULS	CC	
1505	5 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701673	TYLER PULS	CC	
1510	5.4 ± 0.6	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701672	TYLER PULS	CC	
1525	3.6 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701671	TYLER PULS	CC	

RADON TEST REPORT

HIATT MIDDLE SCHOOL
1430 E UNIVERSITY AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1530	2.2 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701670	TYLER PULS	CC	
1535	2.7 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701669	TYLER PULS	CC	
1540	3 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701667	TYLER PULS	CC	
1545	3.4 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701666	TYLER PULS	CC	
1605	3.9 ± 0.5	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701655	TYLER PULS	CC	
1610	2.3 ± 0.4	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701653	TYLER PULS	CC	
1640	3.6 ± 0.5	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701656	TYLER PULS	CC	
1655	3.6 ± 0.4	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701654	TYLER PULS	CC	
1675	3.3 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701675	TYLER PULS	CC	
1690	3.1 ± 0.5	1	2016-02-01	1:00 pm	2016-02-05	1:00 pm	7701679	TYLER PULS	CC	
1700	2.1 ± 0.4	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701657	TYLER PULS	CC	
1705	2.4 ± 0.4	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701659	TYLER PULS	CC	
1710	2.6 ± 0.4	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701660	TYLER PULS	CC	
1725	2.7 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701661	TYLER PULS	CC	
1730	2.3 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701662	TYLER PULS	CC	
1735	3 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701663	TYLER PULS	CC	
1740	2.5 ± 0.4	1	2016-02-01	1:00 pm	2016-02-05	12:00 pm	7701664	TYLER PULS	CC	
1800	0.8 ± 0.3	1	2016-02-01	12:00 pm	2016-02-05	12:00 pm	7701652	TYLER PULS	CC	
1820	0.7 ± 0.3	1	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701717	TYLER PULS	CC	
2020	1.8 ± 0.3	2	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701716	TYLER PULS	CC	
2100	1.9 ± 0.4	2	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701712	TYLER PULS	CC	
2235	2.8 ± 0.4	2	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701713	TYLER PULS	CC	
2440	1.8 ± 0.3	2	2016-02-01	2:00 pm	2016-02-05	1:00 pm	7701714	TYLER PULS	CC	

RADON TEST REPORT

HIATT MIDDLE SCHOOL
1430 E UNIVERSITY AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HILLIS ELEMENTARY
2401 56TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
133	4.6 ± 0.6	1	2016-03-21	1:00 pm	2016-03-25	12:00 pm	7701938	TYLER PULS	CC	
114	2.4 ±	1	2015-01-23		2015-05-11		4937596	CONSULTANT	AT	
114	2.8 ±	1	2015-01-23		2015-05-11		4937627	CONSULTANT	AT	
114	3.2 ±	1	2014-12-02		2014-12-11		4676255	CONSULTANT	CC	
114	4.8 ±	1	2014-12-02		2014-12-11		4676266	CONSULTANT	CC	
117	2.5 ±	1	2014-12-02		2014-12-11		4676256	CONSULTANT	CC	
122	1.6 ±	1	2014-12-02		2014-12-11		4676260	CONSULTANT	CC	
133	1.4 ±	1	2014-12-02		2014-12-11		4676232	CONSULTANT	CC	
134	1.4 ±	1	2014-12-02		2014-12-11		4676263	CONSULTANT	CC	
146	2.5 ±	1	2014-12-02		2014-12-11		7014703	CONSULTANT	CC	
146	2.6 ±	1	2014-12-02		2014-12-11		7014702	CONSULTANT	CC	
149	2.2 ±	1	2014-12-02		2014-12-11		7014701	CONSULTANT	CC	
172	2.6 ±	1	2014-12-02		2014-12-11		7014705	CONSULTANT	CC	
175	2.5 ±	1	2014-12-02		2014-12-11		4676257	CONSULTANT	CC	
180	1 ±	1	2014-12-02		2014-12-11		7014704	CONSULTANT	CC	
139	2.7 ±	1	2012-03-07		2012-03-09		4542249	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HOOVER HIGH SCHOOL
4800 AURORA AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1060	0.6 ±	1	2014-02-10		2014-02-13		4651646	CONSULTANT	CC	
1100	0.9 ±	1	2014-02-10		2014-02-13		4651649	CONSULTANT	CC	
1115	1.0 ±	1	2014-02-10		2014-02-13		4651650	CONSULTANT	CC	
1130	1.1 ±	1	2014-02-10		2014-02-13		4651648	CONSULTANT	CC	
1150	0.8 ±	1	2014-02-10		2014-02-13		4651643	CONSULTANT	CC	
1175	0.8 ±	1	2014-02-10		2014-02-13		4651647	CONSULTANT	CC	
1186	0.9 ±	1	2014-02-10		2014-02-13		4651642	CONSULTANT	CC	
1195	0.9 ±	1	2014-02-10		2014-02-13		4651627	CONSULTANT	CC	
1305	0.5 ±	1	2014-02-10		2014-02-13		4651636	CONSULTANT	CC	
1310	1.5 ±	1	2014-02-10		2014-02-13		4651632	CONSULTANT	CC	
1370	3.3 ±	1	2014-02-10		2014-02-13		4651641	CONSULTANT	CC	
1381	3.0 ±	1	2014-02-10		2014-02-13		4651638	CONSULTANT	CC	
1385	2.1 ±	1	2014-02-10		2014-02-13		4651635	CONSULTANT	CC	
Auditorium	0.7 ±	1	2014-02-10		2014-02-13		4651623	CONSULTANT	CC	
Auditorium	0.8 ±	1	2014-02-10		2014-02-13		4651634	CONSULTANT	CC	
Library	1.6 ±	1	2014-02-10		2014-02-13		4651640	CONSULTANT	CC	
Library	1.7 ±	1	2014-02-10		2014-02-13		4651639	CONSULTANT	CC	
Main Office	0.6 ±	1	2014-02-10		2014-02-13		4651645	CONSULTANT	CC	
Small Gym	0.9 ±	1	2014-02-10		2014-02-13		4651628	CONSULTANT	CC	
Small Gym	1.3 ±	1	2014-02-10		2014-02-13		4651637	CONSULTANT	CC	

RADON TEST REPORT

HOOVER HIGH SCHOOL
4800 AURORA AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HOWE ELEMENTARY
2900 INDIANOLA RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
101	0.7 ±	1	2014-04-07		2014-04-10		4651238	CONSULTANT	CC	
102	1.1 ±	1	2014-04-07		2014-04-10		4651233	CONSULTANT	CC	
103	1.1 ±	1	2014-04-07		2014-04-10		4651240	CONSULTANT	CC	
104	0.5 ±	1	2014-04-07		2014-04-10		4651232	CONSULTANT	CC	
107	0.7 ±	1	2014-04-07		2014-04-10		4651242	CONSULTANT	CC	
108	0.4 ±	1	2014-04-07		2014-04-10		4651235	CONSULTANT	CC	
GYM 004	2.9 ±	0	2014-04-07		2014-04-10		4651239	CONSULTANT	CC	
GYM 004	4.6 ±	0	2014-04-07		2014-04-10		4651237	CONSULTANT	CC	
107	1.6 ±	1	2014-04-01		2014-04-04			CONSULTANT	CRM	
101	5.6 ±	1	2013-03-21		2013-06-27		4894915	CONSULTANT	AT	
102	5.9 ±	1	2013-03-21		2013-06-27		4894921	CONSULTANT	AT	
103	7.7 ±	1	2013-03-21		2013-06-27		4894899	CONSULTANT	AT	
104	4.9 ±	1	2013-03-21		2013-06-27		4894961	CONSULTANT	AT	
Gym	9.2 ±	0	2013-03-21		2013-06-27		4894938	CONSULTANT	AT	
101	7.0 ±	1	2013-02-25		2013-02-28		4600275	CONSULTANT	CC	
102	6.7 ±	1	2013-02-25		2013-02-28		4600274	CONSULTANT	CC	
103	6.8 ±	1	2013-02-25		2013-02-28		4600279	CONSULTANT	CC	
104	5.6 ±	1	2013-02-25		2013-02-28		4600281	CONSULTANT	CC	
107	4.3 ±	1	2013-02-25		2013-02-28		4600282	CONSULTANT	CC	
108	4.7 ±	1	2013-02-25		2013-02-28		4600276	CONSULTANT	CC	
109	3.5 ±	1	2013-02-25		2013-02-28		4600265	CONSULTANT	CC	
110	3.2 ±	1	2013-02-25		2013-02-28		4600272	CONSULTANT	CC	
111	3.7 ±	1	2013-02-25		2013-02-28		4600271	CONSULTANT	CC	
112	2.0 ±	1	2013-02-25		2013-02-28		4600266	CONSULTANT	CC	
Gym	13.4 ±	0	2013-02-25		2013-02-28		4600277	CONSULTANT	CC	

RADON TEST REPORT

HOWE ELEMENTARY
2900 INDIANOLA RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HOYT MIDDLE SCHOOL
2700 E 42ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1420	2.0 \pm	1	2014-02-28		2014-07-25		4924326	CONSULTANT	AT	
1430	1.7 \pm	1	2014-02-28		2014-07-25		4923000	CONSULTANT	AT	
1445	2.3 \pm	1	2014-02-28		2014-07-25		4923002	CONSULTANT	AT	
1750	1.5 \pm	1	2014-02-28		2014-07-25		4924348	CONSULTANT	AT	
1120	2.1 \pm	1	2014-01-27		2014-01-30		4725392	CONSULTANT	CC	
1130	2.1 \pm	1	2014-01-27		2014-01-30		4738614	CONSULTANT	CC	
1150	1.9 \pm	1	2014-01-27		2014-01-30		4738613	CONSULTANT	CC	
1240	1.7 \pm	1	2014-01-27		2014-01-30		4725393	CONSULTANT	CC	
1325	3.0 \pm	1	2014-01-27		2014-01-30		4738624	CONSULTANT	CC	
1350	2.2 \pm	1	2014-01-27		2014-01-30		4738601	CONSULTANT	CC	
1360	1.9 \pm	1	2014-01-27		2014-01-30		4738619	CONSULTANT	CC	
1420	4.1 \pm	1	2014-01-27		2014-01-30		4738625	CONSULTANT	CC	
1430	4.6 \pm	1	2014-01-27		2014-01-30		4738627	CONSULTANT	CC	
1445	4.7 \pm	1	2014-01-27		2014-01-30		4738621	CONSULTANT	CC	
1660	1.7 \pm	1	2014-01-27		2014-01-30		4738620	CONSULTANT	CC	
1750	4.2 \pm	1	2014-01-27		2014-01-30		4738629	CONSULTANT	CC	
Auditorium	1.3 \pm	1	2014-01-27		2014-01-30		4738612	CONSULTANT	CC	
Cafeteria	1.7 \pm	1	2014-01-27		2014-01-30		4738630	CONSULTANT	CC	
Gym	3.0 \pm	1	2014-01-27		2014-01-30		4738617	CONSULTANT	CC	

RADON TEST REPORT

HOYT MIDDLE SCHOOL
2700 E 42ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

HUBBELL ELEMENTARY
800 42ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
106	1.8 ±	1	2013-02-19		2013-02-21		4600187	CONSULTANT	CC	
108	3.1 ±	1	2013-02-19		2013-02-21		4600195	CONSULTANT	CC	
109	3.3 ±	1	2013-02-19		2013-02-21		4600189	CONSULTANT	CC	
112	2.7 ±	1	2013-02-19		2013-02-21		4600193	CONSULTANT	CC	
117	2.4 ±	1	2013-02-19		2013-02-21		4600176	CONSULTANT	CC	
118	3.6 ±	1	2013-02-19		2013-02-21		4600194	CONSULTANT	CC	
119	2.2 ±	1	2013-02-19		2013-02-21		4600196	CONSULTANT	CC	
Cafeteria	1.7 ±	0	2013-02-19		2013-02-21		4600192	CONSULTANT	CC	
Gym	<0.3 ±	0	2013-02-19		2013-02-21		4600186	CONSULTANT	CC	
Office	3.2 ±	1	2013-02-19		2013-02-21		4600190	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

JACKSON ELEMENTARY
3825 INDIANOLA AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1000	5.8 ± 0.6	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701601	TYLER PULS	CC	
1001	5.9 ± 0.6	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701602	TYLER PULS	CC	
1002	6.2 ± 0.6	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701603	TYLER PULS	CC	
1003	4.7 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701605	TYLER PULS	CC	
1004	3.8 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701600	TYLER PULS	CC	
1005	3.7 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701599	TYLER PULS	CC	
1006	4.5 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701598	TYLER PULS	CC	
1007	3.6 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701597	TYLER PULS	CC	
1008	3.9 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701596	TYLER PULS	CC	
1009	5.3 ± 0.6	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701606	TYLER PULS	CC	
1010	4.2 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701607	TYLER PULS	CC	
1011	4.8 ± 0.6	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701608	TYLER PULS	CC	
1012	3.3 ± 0.5	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701615	TYLER PULS	CC	
1013	3.7 ± 0.5	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701614	TYLER PULS	CC	
1014	3.4 ± 0.5	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701612	TYLER PULS	CC	
1015	3.5 ± 0.5	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701611	TYLER PULS	CC	
1016	3.9 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701610	TYLER PULS	CC	
1017	3.4 ± 0.5	1	2016-01-26	12:00 pm	2016-01-29	12:00 pm	7701609	TYLER PULS	CC	
1019	2 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701617	TYLER PULS	CC	
1020	2 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701620	TYLER PULS	CC	
1020A	1.9 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701621	TYLER PULS	CC	
1021	1.6 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701624	TYLER PULS	CC	
1022	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701625	TYLER PULS	CC	
1023	1.2 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701630	TYLER PULS	CC	
1024	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701645	TYLER PULS	CC	
1024A	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701646	TYLER PULS	CC	
1025	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701637	TYLER PULS	CC	
1026	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701638	TYLER PULS	CC	
1027	0.6 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701639	TYLER PULS	CC	
1028	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701640	TYLER PULS	CC	
1029	0.6 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701643	TYLER PULS	CC	
1030	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701644	TYLER PULS	CC	

RADON TEST REPORT

JACKSON ELEMENTARY
3825 INDIANOLA AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1031	0.6 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701631	TYLER PULS	CC	
1032	0.8 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701632	TYLER PULS	CC	
1033	1 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701633	TYLER PULS	CC	
1034	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701634	TYLER PULS	CC	
1035	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701635	TYLER PULS	CC	
1036	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701636	TYLER PULS	CC	
1037	< 0.3 ± 0.3	1	2016-01-26	2:00 pm	2016-01-29	1:00 pm	7701647	TYLER PULS	CC	
1038	3.2 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701618	TYLER PULS	CC	
1040	1.2 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701623	TYLER PULS	CC	
1051	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701641	TYLER PULS	CC	
1095	1.7 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701626	TYLER PULS	CC	
1096	< 0.3 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	12:00 pm	7701628	TYLER PULS	CC	2
1100	1.1 ± 0.3	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701619	TYLER PULS	CC	
1101	2.8 ± 0.4	1	2016-01-26	1:00 pm	2016-01-29	1:00 pm	7701622	TYLER PULS	CC	
1004	5.5 ±	1	2014-03-05		2014-07-25		4937645	CONSULTANT	AT	
1006	5.2 ±	1	2014-03-05		2014-07-25		4937616	CONSULTANT	AT	
1008	±	1	2014-03-05				4937668	CONSULTANT	AT	2
1014	4.7 ±	1	2014-03-05		2014-07-25		4937642	CONSULTANT	AT	
1028	4.4 ±	1	2014-03-05		2014-07-25		4937594	CONSULTANT	AT	
1035	4.2 ±	1	2014-03-05		2014-07-25		4937601	CONSULTANT	AT	
Music	5.8 ±	1	2014-03-05		2014-07-25		4937548	CONSULTANT	AT	
1004	6.3 ±	1	2014-01-28		2014-01-31		4651557	CONSULTANT	CC	
1006	6.0 ±	1	2014-01-28		2014-01-31		4651558	CONSULTANT	CC	
1008	5.7 ±	1	2014-01-28		2014-01-31		4651579	CONSULTANT	CC	
1014	6.4 ±	1	2014-01-28		2014-01-31		4651580	CONSULTANT	CC	
1028	4.5 ±	1	2014-01-28		2014-01-31		4651591	CONSULTANT	CC	
1034	3.8 ±	1	2014-01-28		2014-01-31		4651588	CONSULTANT	CC	
1035	4.2 ±	1	2014-01-28		2014-01-31		4651589	CONSULTANT	CC	
Art	3.9 ±	1	2014-01-28		2014-01-31		4651590	CONSULTANT	CC	
Library	3.5 ±	1	2014-01-28		2014-01-31		4651586	CONSULTANT	CC	
Music	5.4 ±	1	2014-01-28		2014-01-31		4651585	CONSULTANT	CC	

RADON TEST REPORT

JACKSON ELEMENTARY
3825 INDIANOLA AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

JEFFERSON ELEMENTARY
2425 WATROUS AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1105	2.9 ±	1	2014-03-05		2014-07-25		4937610	CONSULTANT	AT	
1105	5.9 ±	1	2014-02-04		2014-02-07		4738602	CONSULTANT	CC	
1120	3.3 ±	1	2014-02-04		2014-02-07		4651592	CONSULTANT	CC	
1200	3.6 ±	1	2014-02-04		2014-02-07		4651511	CONSULTANT	CC	
1210	3.4 ±	1	2014-02-04		2014-02-07		4651515	CONSULTANT	CC	
1220	3.9 ±	1	2014-02-04		2014-02-07		4651516	CONSULTANT	CC	
1415	3.8 ±	1	2014-02-04		2014-02-07		4651529	CONSULTANT	CC	
Gym	1.8 ±	0	2014-02-04		2014-02-07		4651524	CONSULTANT	CC	
Gym	1.9 ±	0	2014-02-04		2014-02-07		4651525	CONSULTANT	CC	
Library	3.6 ±	1	2014-02-04		2014-02-07		4651534	CONSULTANT	CC	
Music	3.6 ±	0	2014-02-04		2014-02-07		4651521	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

JESSE FRANKLIN TAYLOR
1801 16TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1000	1 ± 0.2	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701247	TYLER PULS	CC	
1000A	0.9 ± 0.2	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701248	TYLER PULS	CC	
1020	1.8 ± 0.3	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701243	TYLER PULS	CC	
1025	1 ± 0.2	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701241	TYLER PULS	CC	
1030	1 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701239	TYLER PULS	CC	
1035	0.9 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701237	TYLER PULS	CC	
1040	1.1 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701235	TYLER PULS	CC	
1045	1.4 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701234	TYLER PULS	CC	
1050	1 ± 0.2	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701244	TYLER PULS	CC	
1055	1.1 ± 0.2	1	2015-12-01	1:00 pm	2015-12-04	2:00 pm	7701242	TYLER PULS	CC	
1060	1.2 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701240	TYLER PULS	CC	
1065	0.8 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701238	TYLER PULS	CC	
1070	0.8 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701236	TYLER PULS	CC	
1085	1.4 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701232	TYLER PULS	CC	
2005	1.1 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701228	TYLER PULS	CC	
2010	1.5 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701229	TYLER PULS	CC	
2015	1.5 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701231	TYLER PULS	CC	
2020	1.4 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701230	TYLER PULS	CC	
2040	1.4 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701226	TYLER PULS	CC	
2050	2 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701227	TYLER PULS	CC	
3005	1.3 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701224	TYLER PULS	CC	
3015	1.5 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701223	TYLER PULS	CC	
3025	1.3 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701225	TYLER PULS	CC	
3030	1.5 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701219	TYLER PULS	CC	
3045	1.1 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701217	TYLER PULS	CC	
3050	1.3 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701215	TYLER PULS	CC	
3055	1 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701213	TYLER PULS	CC	
3060	1.7 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701222	TYLER PULS	CC	
3065	1.4 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701220	TYLER PULS	CC	
3070	0.8 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701218	TYLER PULS	CC	1
3075	0.9 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701216	TYLER PULS	CC	
3080	0.9 ± 0.2	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701214	TYLER PULS	CC	

RADON TEST REPORT

JESSE FRANKLIN TAYLOR
1801 16TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
3085	2.1 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701211	TYLER PULS	CC	
3085A	2.3 ± 0.3	1	2015-12-01	12:00 pm	2015-12-04	1:00 pm	7701212	TYLER PULS	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

KING ELEMENTARY
1849 FOREST AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
109	3.8 ±	1	2014-04-07		2014-07-25		4937628	CONSULTANT	AT	
109	5.4 ±	1	2014-03-24		2014-03-27		4651218	CONSULTANT	CC	
1154	2.7 ±	1	2014-03-24		2014-03-27		4651211	CONSULTANT	CC	
117	2.2 ±	1	2014-03-24		2014-03-27		4651215	CONSULTANT	CC	
119	2.2 ±	1	2014-03-24		2014-03-27		4651217	CONSULTANT	CC	
122	1.8 ±	1	2014-03-24		2014-03-27		4651213	CONSULTANT	CC	
132	3.5 ±	1	2014-03-24		2014-03-27		4651210	CONSULTANT	CC	
134	2.9 ±	1	2014-03-24		2014-03-27		4651216	CONSULTANT	CC	
138	1.6 ±	1	2014-03-24		2014-03-27		4651209	CONSULTANT	CC	
141	1.6 ±	1	2014-03-24		2014-03-27		4651220	CONSULTANT	CC	
148	1.0 ±	1	2014-03-24		2014-03-27		4651219	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

LINCOLN HIGH SCHOOL
2600 SW 9TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1110	2.5 \pm	1	2013-02-11		2013-02-14		4600106	CONSULTANT	CC	
1140	1.4 \pm	1	2013-02-11		2013-02-14		4600116	CONSULTANT	CC	
1200	0.8 \pm	1	2013-02-11		2013-02-14		4600118	CONSULTANT	CC	
1210	0.6 \pm	1	2013-02-11		2013-02-14		4600129	CONSULTANT	CC	
1240	0.6 \pm	1	2013-02-11		2013-02-14		4600122	CONSULTANT	CC	
1260	1.2 \pm	1	2013-02-11		2013-02-14		4600130	CONSULTANT	CC	
1290	1.2 \pm	1	2013-02-11		2013-02-14		4600126	CONSULTANT	CC	
1310	1.3 \pm	1	2013-02-11		2013-02-14		4600123	CONSULTANT	CC	
1380	0.9 \pm	1	2013-02-11		2013-02-14		4600128	CONSULTANT	CC	
1390	1.4 \pm	1	2013-02-11		2013-02-14		4600127	CONSULTANT	CC	
1430	1.4 \pm	1	2013-02-11		2013-02-14		4600117	CONSULTANT	CC	
2030	1.6 \pm	1	2013-02-11		2013-02-14		4600112	CONSULTANT	CC	
2110	2.0 \pm	1	2013-02-11		2013-02-14		4600114	CONSULTANT	CC	
2120	2.2 \pm	1	2013-02-11		2013-02-14		4600103	CONSULTANT	CC	
2200	1.5 \pm	1	2013-02-11		2013-02-14		4600101	CONSULTANT	CC	
2220	1.5 \pm	1	2013-02-11		2013-02-14		4600110	CONSULTANT	CC	
2360	1.6 \pm	1	2013-02-11		2013-02-14		4600108	CONSULTANT	CC	
Auditorium	2.0 \pm	1	2013-02-11		2013-02-14		4600124	CONSULTANT	CC	
Gym E	0.8 \pm	1	2013-02-11		2013-02-14		4600102	CONSULTANT	CC	
Gym W	0.9 \pm	1	2013-02-11		2013-02-14		4600125	CONSULTANT	CC	
Library	1.3 \pm	1	2013-02-11		2013-02-14		4600115	CONSULTANT	CC	
Main Office	2.1 \pm	1	2013-02-11		2013-02-14		4600105	CONSULTANT	CC	

RADON TEST REPORT

LINCOLN HIGH SCHOOL
2600 SW 9TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

LOVEJOY ELEMENTARY
801 E KENYON AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1055	1.9 ±	1	2014-03-05		2014-07-25		4937586	CONSULTANT	AT	
1235	1.7 ±	1	2014-03-05		2014-07-25		4937674	CONSULTANT	AT	
Music	1.8 ±	1	2014-03-05		2014-07-25		4937639	CONSULTANT	AT	
1055	5.2 ±	1	2014-02-03		2014-02-06		4651320	CONSULTANT	CC	
1095	3.7 ±	1	2014-02-03		2014-02-06		4651319	CONSULTANT	CC	
1115	3.6 ±	1	2014-02-03		2014-02-06		4651318	CONSULTANT	CC	
1200	3.8 ±	1	2014-02-03		2014-02-06		4651326	CONSULTANT	CC	
1235	5.6 ±	1	2014-02-03		2014-02-06		4651322	CONSULTANT	CC	
1285	3.9 ±	1	2014-02-03		2014-02-06		4651321	CONSULTANT	CC	
1505	5.0 ±	1	2014-02-03		2014-02-06		4651327	CONSULTANT	CC	
Art	3.0 ±	1	2014-02-03		2014-02-06		4651324	CONSULTANT	CC	
Gym	1.3 ±	1	2014-02-03		2014-02-06		4651328	CONSULTANT	CC	
Library	3.2 ±	1	2014-02-03		2014-02-06		4651323	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MADISON ELEMENTARY
806 HOFFMAN AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
106	0.9 ± 0.3	1	2016-03-21	2:00 pm	2016-03-25	2:00 pm	7701948	TYLER PULS	CC	
102	0.7 ±	1	2014-02-11		2014-02-14		4651700	CONSULTANT	CC	
103	0.7 ±	1	2014-02-11		2014-02-14		4651402	CONSULTANT	CC	
106	1.3 ±	1	2014-02-11		2014-02-14		4651403	CONSULTANT	CC	
117	2.6 ±	1	2014-02-11		2014-02-14		4651697	CONSULTANT	CC	
120	2.1 ±	1	2014-02-11		2014-02-14		4651698	CONSULTANT	CC	
125	2.8 ±	1	2014-02-11		2014-02-14		4651696	CONSULTANT	CC	
131	1.3 ±	1	2014-02-11		2014-02-14		4651699	CONSULTANT	CC	
Gym	1.8 ±	1	2014-02-11		2014-02-14		4651695	CONSULTANT	CC	
Gym	2.0 ±	1	2014-02-11		2014-02-14		4651405	CONSULTANT	CC	
Library	1.0 ±	1	2014-02-11		2014-02-14		4651404	CONSULTANT	CC	
120	1.2 ±	1	2012-03-07		2012-03-08		4542250	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

AG FACILITY
201 COUNTY LINE RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1	< 0.3 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701770	TYLER PULS	CC	
2	< 0.3 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701773	TYLER PULS	CC	
5	< 0.3 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701771	TYLER PULS	CC	
6	< 0.3 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701772	TYLER PULS	CC	
HB-1	1 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701776	TYLER PULS	CC	
HB-2	1.3 ± 0.2	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701775	TYLER PULS	CC	2
HB-3	2.3 ± 0.3	1	2016-02-09	1:00 pm	2016-02-12	1:00 pm	7701780	TYLER PULS	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MCCOMBS MIDDLE SCHOOL
201 COUNTY LINE RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1005	2.1 ±	1	2014-02-10		2014-02-12		7014778	CONSULTANT	CC	
1101	3.0 ±	1	2014-02-10		2014-02-12		7014777	CONSULTANT	CC	
1108	2.5 ±	1	2014-02-10		2014-02-12		7014771	CONSULTANT	CC	
1201	2.2 ±	1	2014-02-10		2014-02-12		7014776	CONSULTANT	CC	
1201	3.1 ±	1	2014-02-10		2014-02-12		7014769	CONSULTANT	CC	
1312	1.6 ±	1	2014-02-10		2014-02-12		7014772	CONSULTANT	CC	
1325	1.7 ±	1	2014-02-10		2014-02-12		7014775	CONSULTANT	CC	
1401	2.2 ±	1	2014-02-10		2014-02-12		7014780	CONSULTANT	CC	
1401	2 ±	1	2014-02-10		2014-02-12		7014783	CONSULTANT	CC	
1513	2.5 ±	1	2014-02-10		2014-02-12		7014770	CONSULTANT	CC	
1525	5 ±	1	2014-02-10		2014-02-12		7014784	CONSULTANT	CC	
1632	3.8 ±	1	2014-02-10		2014-02-12		7014774	CONSULTANT	CC	
1525	3.8 ±	1	2014-01-23		2015-01-23		4937653	CONSULTANT	AT	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MCKEE EDUCATION CENTER
2115 E 39TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
102	3.1 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701258	TYLER PULS	CC	
105	2.9 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701262	TYLER PULS	CC	
106	2.9 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701264	TYLER PULS	CC	
107	2.7 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701266	TYLER PULS	CC	
108	0.9 ± 0.2	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701267	TYLER PULS	CC	
108A	1.3 ± 0.2	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701268	TYLER PULS	CC	
111	2.2 ± 0.3	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701271	TYLER PULS	CC	
113	2.1 ± 0.3	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701273	TYLER PULS	CC	
114	1.4 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701269	TYLER PULS	CC	
114A	1.2 ± 0.2	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701270	TYLER PULS	CC	
117	2.1 ± 0.3	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701283	TYLER PULS	CC	
12	1.4 ± 0.2	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701275	TYLER PULS	CC	
13	1.4 ± 0.2	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701281	TYLER PULS	CC	
134	2.4 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701265	TYLER PULS	CC	
136	2.9 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701263	TYLER PULS	CC	
14	1.3 ± 0.2	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701279	TYLER PULS	CC	
141	2.8 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701261	TYLER PULS	CC	
146	3.3 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701259	TYLER PULS	CC	
147	3.1 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701260	TYLER PULS	CC	
15	1.2 ± 0.2	1	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701274	TYLER PULS	CC	
158	4 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701254	TYLER PULS	CC	1
162	3.4 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701253	TYLER PULS	CC	
164	3.8 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701252	TYLER PULS	CC	
166	4 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701255	TYLER PULS	CC	
167	3.5 ± 0.3	1	2015-12-07	11:00 am	2015-12-11	11:00 am	7701256	TYLER PULS	CC	
22	1.2 ± 0.2	2	2015-12-07	12:00 pm	2015-12-11	11:00 am	7701282	TYLER PULS	CC	

RADON TEST REPORT

MCKEE EDUCATION CENTER
2115 E 39TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MCKINLEY ELEMENTARY
1610 SE 6TH ST



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
B09	3.6 ±	0	2016-03-22	11:58	2016-03-25	12:58		TYLER PULS	CRM	
B08	9.3 ±	0	2016-03-09	11:12	2016-03-11	13:12		TYLER PULS	CRM	
B08	8.5 ±	0	2016-02-29	8:02	2016-03-02	10:02		TYLER PULS	CRM	
B08	10.2 ±	0	2016-02-24	14:25	2016-02-26	14:25		TYLER PULS	CRM	
B08	18.6 ±	0	2016-02-22	10:19	2016-02-24	10:19		TYLER PULS	CRM	
100	5.8 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701745	TYLER PULS	CC	
101	4.4 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701740	TYLER PULS	CC	
102	4.9 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701742	TYLER PULS	CC	
103	4.2 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701741	TYLER PULS	CC	
104	4 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701738	TYLER PULS	CC	
105	4.6 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701739	TYLER PULS	CC	
106	2 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701735	TYLER PULS	CC	
107	4.7 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701750	TYLER PULS	CC	
109	3.7 ± 0.4	1	2016-02-09	11:00 am	2016-02-12	10:00 am	7701764	TYLER PULS	CC	
112	2.7 ± 0.3	1	2016-02-09	11:00 am	2016-02-12	10:00 am	7701763	TYLER PULS	CC	
114	3.3 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701746	TYLER PULS	CC	
114A	4.3 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701748	TYLER PULS	CC	
114B	3.5 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701749	TYLER PULS	CC	
115	4.6 ± 0.4	1	2016-02-09	11:00 am	2016-02-12	10:00 am	7701768	TYLER PULS	CC	
116	3.3 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701747	TYLER PULS	CC	
117	2.8 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701736	TYLER PULS	CC	
118A	4.4 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701737	TYLER PULS	CC	
119	2.4 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701732	TYLER PULS	CC	
120	2.3 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701725	TYLER PULS	CC	
121	3 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701723	TYLER PULS	CC	
122	3.1 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701721	TYLER PULS	CC	
123	3.2 ± 0.3	1	2016-02-09	9:00 am	2016-02-12	10:00 am	7701718	TYLER PULS	CC	
124	2.4 ± 0.3	1	2016-02-09	9:00 am	2016-02-12	10:00 am	7701719	TYLER PULS	CC	
125	2.4 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701720	TYLER PULS	CC	
126	2.3 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701722	TYLER PULS	CC	
127	3.5 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701726	TYLER PULS	CC	
128	6.1 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701743	TYLER PULS	CC	

RADON TEST REPORT

MCKINLEY ELEMENTARY
1610 SE 6TH ST



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
132	2.8 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701730	TYLER PULS	CC	
132A	2.9 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701731	TYLER PULS	CC	
133	5.5 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701727	TYLER PULS	CC	
134	4.2 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701729	TYLER PULS	CC	
135	3.7 ± 0.4	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701733	TYLER PULS	CC	
149	1.8 ± 0.3	1	2016-02-09	10:00 am	2016-02-12	10:00 am	7701734	TYLER PULS	CC	
206	4.9 ± 0.4	2	2016-02-09	11:00 am	2016-02-12	10:00 am	7701767	TYLER PULS	CC	
217	4.1 ± 0.4	2	2016-02-09	11:00 am	2016-02-12	10:00 am	7701765	TYLER PULS	CC	
B01	5.3 ± 0.4	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701754	TYLER PULS	CC	
B03	4.1 ± 0.4	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701756	TYLER PULS	CC	
B05	3.2 ± 0.3	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701759	TYLER PULS	CC	
B06	3.2 ± 0.3	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701760	TYLER PULS	CC	
B08	8.6 ± 0.5	0	2016-02-09	10:00 am	2016-02-12	10:00 am	7701751	TYLER PULS	CC	
B09	5.1 ± 0.4	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701753	TYLER PULS	CC	
B16	3 ± 0.3	0	2016-02-09	11:00 am	2016-02-12	10:00 am	7701761	TYLER PULS	CC	
106	3.8 ±	1	2014-03-03		2014-07-25		4937552	CONSULTANT	AT	
107	4.6 ±	1	2014-03-03		2014-07-25		4924320	CONSULTANT	AT	
122	4.1 ±	1	2014-03-03		2014-07-25		4937609	CONSULTANT	AT	
127	3.6 ±	1	2014-03-03		2014-07-25		4937615	CONSULTANT	AT	
128	6.1 ±	1	2014-03-03		2014-03-06		4651441	CONSULTANT	CC	
Art	4.9 ±	0	2014-03-03		2014-07-25		4924365	CONSULTANT	AT	
B03	±	0	2014-03-03				4937567	CONSULTANT	AT	2
Music	6.9 ±	0	2014-03-03		2014-03-06		4651442	CONSULTANT	CC	
106	4.8 ±	1	2014-01-28		2014-01-31		4651568	CONSULTANT	CC	
107	6.6 ±	1	2014-01-28		2014-01-31		4651569	CONSULTANT	CC	
120	3.4 ±	1	2014-01-28		2014-01-31		4651562	CONSULTANT	CC	
122	4.0 ±	1	2014-01-28		2014-01-31		4651561	CONSULTANT	CC	
124	3.9 ±	1	2014-01-28		2014-01-31		4651559	CONSULTANT	CC	
127	7.3 ±	1	2014-01-28		2014-01-31		4651560	CONSULTANT	CC	
128	8.0 ±	1	2014-01-28		2014-01-31		4651564	CONSULTANT	CC	
Art	4.8 ±	0	2014-01-28		2014-01-31		4651570	CONSULTANT	CC	
B03	7.1 ±	0	2014-01-28		2014-01-31		4651582	CONSULTANT	CC	

RADON TEST REPORT

MCKINLEY ELEMENTARY
1610 SE 6TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
Music	9.4 ±	0	2014-01-28		2014-01-31		4651581	CONSULTANT	CC	
123	3.1 ±	1	2011-11-28		2012-03-05		4837134	CONSULTANT	AT	
123	5.1 ±	1	2011-11-07		2011-11-10		4542205	CONSULTANT	CC	
124	1.7 ±	1	2011-11-07		2011-11-10		4448649	CONSULTANT	CC	
Gym	1.1 ±	1	2011-11-07		2011-11-10		4448648	CONSULTANT	CC	
Gym	1.3 ±	1	2011-11-07		2011-11-10		4542208	CONSULTANT	CC	
Nurse	3.9 ±	1	2011-11-07		2011-11-10		4542206	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MEREDITH MIDDLE SCHOOL
4827 MADISON AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
5105	6.4 ±	1	2014-03-03		2014-03-06		4651432	CONSULTANT	CC	
5115	1.7 ±	1	2014-03-03		2014-07-25		4937643	CONSULTANT	AT	
5290	1.6 ±	1	2014-03-03		2014-07-25		4937634	CONSULTANT	AT	
5700	3 ±	1	2014-03-03		2014-07-25		4937580	CONSULTANT	AT	
5720	4.0 ±	1	2014-03-03		2014-03-06		4651444	CONSULTANT	CC	
5735	4.5 ±	1	2014-03-03		2014-03-06		4651429	CONSULTANT	CC	
5905	1.5 ±	1	2014-03-03		2014-07-25		4937564	CONSULTANT	AT	
5920	1.7 ±	1	2014-03-03		2014-07-25		4937606	CONSULTANT	AT	
5935	1.6 ±	1	2014-03-03		2014-07-25		4937669	CONSULTANT	AT	
5105	1.5 ±	1	2014-03-01		2014-03-02			CONSULTANT	CRM	
5105	8.8 ±	1	2014-02-10		2014-02-13		4651630	CONSULTANT	CC	
5115	4.9 ±	1	2014-02-10		2014-02-13		4651625	CONSULTANT	CC	
5135	3.4 ±	1	2014-02-10		2014-02-13		4651629	CONSULTANT	CC	
5235	2.8 ±	1	2014-02-10		2014-02-13		4651616	CONSULTANT	CC	
5290	6.2 ±	1	2014-02-10		2014-02-13		4651614	CONSULTANT	CC	
5505	2.8 ±	1	2014-02-10		2014-02-13		4651615	CONSULTANT	CC	
5585	2.3 ±	1	2014-02-10		2014-02-13		4651617	CONSULTANT	CC	
5700	7.4 ±	1	2014-02-10		2014-02-13		4651626	CONSULTANT	CC	
5720	9.2 ±	1	2014-02-10		2014-02-13		4651620	CONSULTANT	CC	
5735	8.1 ±	1	2014-02-10		2014-02-13		4651621	CONSULTANT	CC	
5905	7.4 ±	1	2014-02-10		2014-02-13		4651631	CONSULTANT	CC	
5920	4.5 ±	1	2014-02-10		2014-02-13		4651622	CONSULTANT	CC	
5935	5.1 ±	1	2014-02-10		2014-02-13		4651624	CONSULTANT	CC	
Gym	3.4 ±	1	2014-02-10		2014-02-13		4651618	CONSULTANT	CC	
Gym	3.0 ±	1	2014-02-10		2014-02-13		4651393	CONSULTANT	CC	

RADON TEST REPORT

MEREDITH MIDDLE SCHOOL
4827 MADISON AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MERRILL MIDDLE SCHOOL
5301 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	1.4 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701349	TYLER PULS	CC	
102	1.5 ± 0.3	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701350	TYLER PULS	CC	
103	1.6 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701398	TYLER PULS	CC	
105	1.5 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701345	TYLER PULS	CC	
106	1.4 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701344	TYLER PULS	CC	
107	1.5 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701346	TYLER PULS	CC	
108	1.4 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701400	TYLER PULS	CC	
109	1.6 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701397	TYLER PULS	CC	
110	1.5 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701329	TYLER PULS	CC	
111	1.3 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701328	TYLER PULS	CC	2
112	1.5 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701331	TYLER PULS	CC	
113	1.7 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701330	TYLER PULS	CC	
114	1.8 ± 0.3	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701332	TYLER PULS	CC	
115	1.7 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701334	TYLER PULS	CC	
116	1.6 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701335	TYLER PULS	CC	
117	1.8 ± 0.3	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701336	TYLER PULS	CC	
117A	1.9 ± 0.3	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701337	TYLER PULS	CC	
117B	1.9 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701338	TYLER PULS	CC	
117C	2 ± 0.3	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701339	TYLER PULS	CC	
117D	1.9 ± 0.3	1	2015-12-14	11:00 am	2015-12-18	10:00 am	7701340	TYLER PULS	CC	
118	1.7 ± 0.3	1	2015-12-14	11:00 am	2015-12-18	10:00 am	7701341	TYLER PULS	CC	
119	2.2 ± 0.3	1	2015-12-14	11:00 am	2015-12-18	10:00 am	7701342	TYLER PULS	CC	
121	1.5 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701347	TYLER PULS	CC	
122	1.6 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	10:00 am	7701343	TYLER PULS	CC	
124	1.4 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701399	TYLER PULS	CC	
125	1.6 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701396	TYLER PULS	CC	
125A	1.4 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701395	TYLER PULS	CC	
126	1.3 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701391	TYLER PULS	CC	
127	1.1 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701392	TYLER PULS	CC	
127A	1.1 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701393	TYLER PULS	CC	
128	1.2 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701394	TYLER PULS	CC	2
130	1.5 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701390	TYLER PULS	CC	

RADON TEST REPORT

MERRILL MIDDLE SCHOOL
5301 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
130A	1.8 ± 0.2	1	2015-12-14	11:00 am	2015-12-18	11:00 am	7701389	TYLER PULS	CC	
131	1.4 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701384	TYLER PULS	CC	
131C	1.3 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701382	TYLER PULS	CC	
133	1.4 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701386	TYLER PULS	CC	
135	1.6 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701387	TYLER PULS	CC	
136	1.3 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701381	TYLER PULS	CC	
137	1.7 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701377	TYLER PULS	CC	
141	1.1 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701376	TYLER PULS	CC	
143	1.3 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701380	TYLER PULS	CC	
145	1.1 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701379	TYLER PULS	CC	
146	1.2 ± 0.2	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701378	TYLER PULS	CC	
160	1.7 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701327	TYLER PULS	CC	
162	1.8 ± 0.2	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701326	TYLER PULS	CC	
164	2 ± 0.3	1	2015-12-14	10:00 am	2015-12-18	10:00 am	7701325	TYLER PULS	CC	
213	1.5 ± 0.2	2	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701373	TYLER PULS	CC	
216	1.6 ± 0.2	2	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701371	TYLER PULS	CC	
219	1.4 ± 0.2	2	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701370	TYLER PULS	CC	
221	1.5 ± 0.2	2	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701369	TYLER PULS	CC	
EXER.	2.4 ± 0.3	1	2015-12-14	12:00 pm	2015-12-18	11:00 am	7701388	TYLER PULS	CC	

RADON TEST REPORT

MERRILL MIDDLE SCHOOL
5301 GRAND AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MITCHELL ELEMENTARY
111 PORTER AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	1.7 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701921	TYLER PULS	CC	
101	2.3 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701922	TYLER PULS	CC	
102	4.3 ± 0.6	1	2016-03-21	10:00 am	2016-03-25	10:00 am	7701899	TYLER PULS	CC	
103	2 ± 0.4	1	2016-03-21	10:00 am	2016-03-25	10:00 am	7701902	TYLER PULS	CC	
103A	2 ± 0.4	1	2016-03-21	10:00 am	2016-03-25	10:00 am	7701903	TYLER PULS	CC	
104	2.6 ± 0.4	1	2016-03-21	10:00 am	2016-03-25	10:00 am	7701901	TYLER PULS	CC	
105	1.9 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701905	TYLER PULS	CC	
106	2.5 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701924	TYLER PULS	CC	
107	1.6 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701919	TYLER PULS	CC	
108	1.9 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701925	TYLER PULS	CC	
110	1.8 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701926	TYLER PULS	CC	
112	2.5 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701928	TYLER PULS	CC	
114	2.1 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701931	TYLER PULS	CC	
115	1.4 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701929	TYLER PULS	CC	
118	1.7 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701917	TYLER PULS	CC	
120	2 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701915	TYLER PULS	CC	
122	1.5 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701914	TYLER PULS	CC	
124	1.6 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701912	TYLER PULS	CC	
125	1.1 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701920	TYLER PULS	CC	
126	1.4 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701911	TYLER PULS	CC	
128	1.3 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701910	TYLER PULS	CC	
1290	1.4 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701932	TYLER PULS	CC	
130	1.3 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701918	TYLER PULS	CC	
131	1.3 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701913	TYLER PULS	CC	
132	2 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701923	TYLER PULS	CC	
133	1.8 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701909	TYLER PULS	CC	
135	1.6 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701906	TYLER PULS	CC	
136	0.9 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701907	TYLER PULS	CC	
137	1.5 ± 0.3	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701908	TYLER PULS	CC	
153	1.6 ± 0.4	1	2016-03-21	11:00 am	2016-03-25	10:00 am	7701904	TYLER PULS	CC	
102	2.2 ±	1	2014-04-11		2014-07-25		4937618	CONSULTANT	AT	
104	1.9 ±	1	2014-04-11		2014-07-25		4937678	CONSULTANT	AT	

RADON TEST REPORT

MITCHELL ELEMENTARY
111 PORTER AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
102	4.3 ±	1	2014-03-10		2014-03-13		4651456	CONSULTANT	CC	
104	4.2 ±	1	2014-03-10		2014-03-13		4651464	CONSULTANT	CC	
106	2.4 ±	1	2014-03-10		2014-03-13		4651459	CONSULTANT	CC	
108	2.4 ±	1	2014-03-10		2014-03-13		4651460	CONSULTANT	CC	
110	2.3 ±	1	2014-03-10		2014-03-13		4651461	CONSULTANT	CC	
112	1.6 ±	1	2014-03-10		2014-03-13		4651430	CONSULTANT	CC	
114	1.3 ±	1	2014-03-10		2014-03-13		4651462	CONSULTANT	CC	
115	1.3 ±	1	2014-03-10		2014-03-13		4651455	CONSULTANT	CC	
118	1.6 ±	1	2014-03-10		2014-03-13		4651431	CONSULTANT	CC	
120	2.1 ±	1	2014-03-10		2014-03-13		4651452	CONSULTANT	CC	
122	1.8 ±	1	2014-03-10		2014-03-13		4651454	CONSULTANT	CC	
124	2.6 ±	1	2014-03-10		2014-03-13		4651433	CONSULTANT	CC	
126	1.7 ±	1	2014-03-10		2014-03-13		4651438	CONSULTANT	CC	
128	1.7 ±	1	2014-03-10		2014-03-13		4651427	CONSULTANT	CC	
130	0.8 ±	1	2014-03-10		2014-03-13		4651458	CONSULTANT	CC	
Gym	2.9 ±	1	2014-03-10		2014-03-13		4651425	CONSULTANT	CC	
Gym	2.8 ±	1	2014-03-10		2014-03-13		4651463	CONSULTANT	CC	
106	1.3 ±	1	2012-03-07		2012-03-09		4542271	CONSULTANT	CC	
108	1.1 ±	1	2012-03-07		2012-03-09		4542270	CONSULTANT	CC	
110	1.7 ±	1	2012-03-07		2012-03-09		4542281	CONSULTANT	CC	
112	1.4 ±	1	2012-03-07		2012-03-09		4542279	CONSULTANT	CC	
115	1.1 ±	1	2012-03-07		2012-03-09		4542273	CONSULTANT	CC	
118	0.9 ±	1	2012-03-07		2012-03-09		4542278	CONSULTANT	CC	
120	1.8 ±	1	2012-03-07		2012-03-09		4542272	CONSULTANT	CC	
122	1.1 ±	1	2012-03-07		2012-03-09		4542274	CONSULTANT	CC	
124	1.6 ±	1	2012-03-07		2012-03-09		4542280	CONSULTANT	CC	
126	1 ±	1	2012-03-07		2012-03-09		4542277	CONSULTANT	CC	
128	1.3 ±	1	2012-03-07		2012-03-09		4542275	CONSULTANT	CC	
130	0.9 ±	1	2012-03-07		2012-03-09		4542269	CONSULTANT	CC	
Cafeteria	4.1 ±	1	2011-11-30		2012-03-05		4835996	CONSULTANT	AT	
104	4.3 ±	1	2011-11-10		2011-11-14		4542236	CONSULTANT	CC	
Cafeteria	4.9 ±	1	2011-11-10		2011-11-14		4542225	CONSULTANT	CC	

RADON TEST REPORT

MITCHELL ELEMENTARY
111 PORTER AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
Gym	3.2 ±	1	2011-11-10		2011-11-14		4542234	CONSULTANT	CC	
Gym	3.7 ±	1	2011-11-10		2011-11-14		4542231	CONSULTANT	CC	
Nurse	1.7 ±	1	2011-11-10		2011-11-14		4542224	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MONROE ELEMENTARY
3015 FRANCIS AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
109	0.6 ±	1	2014-03-10		2014-03-13		4738566	CONSULTANT	CC	
116	0.6 ±	1	2014-03-10		2014-03-13		4738562	CONSULTANT	CC	
120	0.8 ±	1	2014-03-10		2014-03-13		4738560	CONSULTANT	CC	
123	0.8 ±	1	2014-03-10		2014-03-13		4738569	CONSULTANT	CC	
125	0.9 ±	1	2014-03-10		2014-03-13		4738559	CONSULTANT	CC	
129	0.8 ±	1	2014-03-10		2014-03-13		4738561	CONSULTANT	CC	
Cafeteria	2.1 ±	1	2014-03-10		2014-03-13		4738563	CONSULTANT	CC	
Gym	0.6 ±	1	2014-03-10		2014-03-13		4738568	CONSULTANT	CC	
Gym	0.5 ±	1	2014-03-10		2014-03-13		4738567	CONSULTANT	CC	
Library	0.6 ±	1	2014-03-10		2014-03-13		4738564	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MOORE ELEMENTARY
3725 52ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1005	0.8 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701284	TYLER PULS	CC	
1010	0.6 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701285	TYLER PULS	CC	
1015	0.7 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701287	TYLER PULS	CC	
1020	0.8 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701286	TYLER PULS	CC	
1025	0.6 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701288	TYLER PULS	CC	
1030	0.9 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701290	TYLER PULS	CC	
1040	0.9 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701291	TYLER PULS	CC	
1045	0.7 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	1:00 pm	7701320	TYLER PULS	CC	
1051	0.7 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	1:00 pm	7701321	TYLER PULS	CC	
1054	0.9 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	1:00 pm	7701322	TYLER PULS	CC	
1055	0.8 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	1:00 pm	7701323	TYLER PULS	CC	
1110	0.8 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	1:00 pm	7701324	TYLER PULS	CC	
1115	1.4 ± 0.3	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701292	TYLER PULS	CC	
1115A	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701293	TYLER PULS	CC	
1125	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701294	TYLER PULS	CC	
1130	1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701296	TYLER PULS	CC	
1135	1.2 ± 0.3	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701297	TYLER PULS	CC	
1140	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701298	TYLER PULS	CC	
1145	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701299	TYLER PULS	CC	
1150	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701300	TYLER PULS	CC	
1155	1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701301	TYLER PULS	CC	
1160	1.2 ± 0.3	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701302	TYLER PULS	CC	
1165	1.1 ± 0.2	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701304	TYLER PULS	CC	
1170	1.8 ± 0.3	1	2015-12-08	12:00 pm	2015-12-11	12:00 pm	7701303	TYLER PULS	CC	
1172	1.5 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701305	TYLER PULS	CC	
1173	1.5 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701306	TYLER PULS	CC	
1175	1.5 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701307	TYLER PULS	CC	
1205	1 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701309	TYLER PULS	CC	
1210	1 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701310	TYLER PULS	CC	
1220	1.5 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701311	TYLER PULS	CC	
1225	1.4 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701312	TYLER PULS	CC	
1235	1.1 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701313	TYLER PULS	CC	

RADON TEST REPORT

MOORE ELEMENTARY
3725 52ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1250	1.3 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701314	TYLER PULS	CC	
1325	1.1 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701319	TYLER PULS	CC	
1330	1.4 ± 0.3	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701315	TYLER PULS	CC	
1335	1.2 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701317	TYLER PULS	CC	
1335A	0.8 ± 0.2	1	2015-12-08	1:00 pm	2015-12-11	12:00 pm	7701318	TYLER PULS	CC	
101	3.7 ±	1	2012-09-24		2012-09-27		4464309	CONSULTANT	CC	
104	4.0 ±	1	2012-09-24		2012-09-27		4464310	CONSULTANT	CC	
107	3.7 ±	1	2012-09-24		2012-09-27		4464307	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

1 = Closed building conditions not maintained throughout testing duration.

2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MORRIS ELEMENTARY
1401 GEIL AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
150	5.0 ±	1	2014-03-05		2014-07-25		4937664	CONSULTANT	AT	
114	3.1 ±	1	2014-02-03		2014-02-06		4651340	CONSULTANT	CC	
125	2.2 ±	1	2014-02-03		2014-02-06		4651341	CONSULTANT	CC	
138	2.9 ±	1	2014-02-03		2014-02-06		4651344	CONSULTANT	CC	
142	3.5 ±	1	2014-02-03		2014-02-06		4651345	CONSULTANT	CC	
150	4.2 ±	1	2014-02-03		2014-02-06		4651349	CONSULTANT	CC	
151	2.4 ±	1	2014-02-03		2014-02-06		4651347	CONSULTANT	CC	
156	2.8 ±	1	2014-02-03		2014-02-06		4651343	CONSULTANT	CC	
171	1.7 ±	1	2014-02-03		2014-02-06		4651348	CONSULTANT	CC	
172	2.0 ±	1	2014-02-03		2014-02-06		4651350	CONSULTANT	CC	
Music	2.0 ±	1	2014-02-03		2014-02-06		4651346	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

MOULTON ELEMENTARY
1541 8TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
104	3.8 ±	1	2014-02-11		2014-02-14		4651684	CONSULTANT	CC	
105	3.3 ±	1	2014-02-11		2014-02-14		4651682	CONSULTANT	CC	
106	2.6 ±	1	2014-02-11		2014-02-14		4651675	CONSULTANT	CC	
107	2.5 ±	1	2014-02-11		2014-02-14		4651672	CONSULTANT	CC	
126	1.6 ±	1	2014-02-11		2014-02-14		4651674	CONSULTANT	CC	
131	2.9 ±	1	2014-02-11		2014-02-14		4651679	CONSULTANT	CC	
134	3.4 ±	1	2014-02-11		2014-02-14		4651677	CONSULTANT	CC	
140	3.8 ±	1	2014-02-11		2014-02-14		4651678	CONSULTANT	CC	
Cafeteria	2.4 ±	1	2014-02-11		2014-02-14		4651683	CONSULTANT	CC	
Cafeteria	2.4 ±	1	2014-02-11		2014-02-14		4651680	CONSULTANT	CC	
104	0.8 ±	1	2011-11-07		2011-11-10		4542219	CONSULTANT	CC	
105	1.1 ±	1	2011-11-07		2011-11-10		4542222	CONSULTANT	CC	
106	1.0 ±	1	2011-11-07		2011-11-10		4542230	CONSULTANT	CC	
Library	1.5 ±	1	2011-11-07		2011-11-10		4542212	CONSULTANT	CC	
Nurse	0.8 ±	1	2011-11-07		2011-11-10		4542215	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

NORTH HIGH SCHOOL
501 HOLCOMB AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1141	1 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701865	TYLER PULS	CC	
1210	0.8 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701873	TYLER PULS	CC	
1210A	0.8 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701866	TYLER PULS	CC	
1210AA	0.5 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701867	TYLER PULS	CC	
1210C	0.6 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701874	TYLER PULS	CC	
1221	0.6 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701875	TYLER PULS	CC	
1223	< 0.3 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701876	TYLER PULS	CC	
1224	0.6 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701877	TYLER PULS	CC	
1231	0.7 ± 0.2	1	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701889	TYLER PULS	CC	
1233	< 0.3 ± 0.2	1	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701887	TYLER PULS	CC	
1235	±	1	2016-02-16	12:00 pm			7701888	TYLER PULS	CC	2
1239	1.4 ± 0.3	1	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701886	TYLER PULS	CC	
1241	0.8 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701878	TYLER PULS	CC	
1242	< 0.3 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701879	TYLER PULS	CC	
1243	0.9 ± 0.3	1	2016-02-16	12:00 pm	2016-02-19	12:00 pm	7701885	TYLER PULS	CC	
1244	0.6 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701880	TYLER PULS	CC	
1245	0.6 ± 0.3	1	2016-02-16	12:00 pm	2016-02-19	12:00 pm	7701882	TYLER PULS	CC	
1246	< 0.3 ± 0.2	1	2016-02-16	12:00 pm	2016-02-19	12:00 pm	7701884	TYLER PULS	CC	
1254	1.6 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701869	TYLER PULS	CC	
1301	1 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701861	TYLER PULS	CC	
1301A	0.9 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701862	TYLER PULS	CC	
1302	0.7 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701863	TYLER PULS	CC	
1321	2.4 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701868	TYLER PULS	CC	
1322	3 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701871	TYLER PULS	CC	
1323	2.5 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701872	TYLER PULS	CC	
1330	0.7 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	1:00 pm	7701858	TYLER PULS	CC	
1340	0.9 ± 0.2	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701857	TYLER PULS	CC	
1401	1.1 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701864	TYLER PULS	CC	
1402	0.9 ± 0.3	1	2016-02-16	11:00 am	2016-02-19	12:00 pm	7701859	TYLER PULS	CC	
2104	1.7 ± 0.3	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701894	TYLER PULS	CC	
2330	0.6 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701892	TYLER PULS	CC	
2404	< 0.3 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701891	TYLER PULS	CC	

RADON TEST REPORT

NORTH HIGH SCHOOL
501 HOLCOMB AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
2423	< 0.3 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701897	TYLER PULS	CC	
2430	< 0.3 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701895	TYLER PULS	CC	
2434	< 0.3 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701898	TYLER PULS	CC	
2501	0.6 ± 0.2	2	2016-02-16	12:00 pm	2016-02-19	1:00 pm	7701890	TYLER PULS	CC	
1000	2.3 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701796	TYLER PULS	CC	
1003	3.5 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701797	TYLER PULS	CC	
1011	1.4 ± 0.2	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701783	TYLER PULS	CC	
1013	1.7 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701782	TYLER PULS	CC	
1014	1.8 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701784	TYLER PULS	CC	
1021	2 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701795	TYLER PULS	CC	
1022	2 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701794	TYLER PULS	CC	
1023	2.7 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701791	TYLER PULS	CC	
1024	2.8 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701789	TYLER PULS	CC	
1025	2.9 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701788	TYLER PULS	CC	
1026	2.5 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701787	TYLER PULS	CC	
1027	1.7 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701786	TYLER PULS	CC	
1032	1.5 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701793	TYLER PULS	CC	
1033	1.9 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701792	TYLER PULS	CC	
1034	1.7 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701790	TYLER PULS	CC	
1035	2.2 ± 0.3	1	2016-02-15	1:00 pm	2016-02-19	1:00 pm	7701785	TYLER PULS	CC	
1110	2.9 ± 0.3	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701810	TYLER PULS	CC	
1111	2.7 ± 0.3	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701809	TYLER PULS	CC	
1121	1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701817	TYLER PULS	CC	
1123	1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701818	TYLER PULS	CC	
1124	0.7 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701819	TYLER PULS	CC	
1125	0.5 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701822	TYLER PULS	CC	
1127	1.1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701820	TYLER PULS	CC	
1128	0.9 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701816	TYLER PULS	CC	
1129	1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701815	TYLER PULS	CC	
1151	1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	1:00 pm	7701798	TYLER PULS	CC	
1152	0.9 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	1:00 pm	7701799	TYLER PULS	CC	
1153	0.9 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	1:00 pm	7701801	TYLER PULS	CC	

RADON TEST REPORT

NORTH HIGH SCHOOL
501 HOLCOMB AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1154	0.8 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	1:00 pm	7701802	TYLER PULS	CC	
1155	0.6 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	1:00 pm	7701803	TYLER PULS	CC	
1156	1.1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701804	TYLER PULS	CC	
1160	1.1 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701805	TYLER PULS	CC	
1161	0.9 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701806	TYLER PULS	CC	
1162	0.7 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701807	TYLER PULS	CC	
1163	±	1	2016-02-15	2:00 pm			7701808	TYLER PULS	CC	2
1171	1.4 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701812	TYLER PULS	CC	
1172	2.2 ± 0.3	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701813	TYLER PULS	CC	
1173	0.8 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701814	TYLER PULS	CC	
1331	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701856	TYLER PULS	CC	
1332	1.1 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701855	TYLER PULS	CC	
1342	0.9 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701851	TYLER PULS	CC	
1343	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701852	TYLER PULS	CC	
1344	0.9 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701850	TYLER PULS	CC	
1403	0.8 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701854	TYLER PULS	CC	
1405	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701853	TYLER PULS	CC	
1406	0.8 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701839	TYLER PULS	CC	
1411	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701836	TYLER PULS	CC	
1411A	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701837	TYLER PULS	CC	
1412	0.8 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701838	TYLER PULS	CC	
1421	< 0.3 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701823	TYLER PULS	CC	
1422	0.6 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701825	TYLER PULS	CC	
1423	0.6 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701826	TYLER PULS	CC	
1424	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701829	TYLER PULS	CC	
1425	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701832	TYLER PULS	CC	
1426	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701833	TYLER PULS	CC	
1430	0.7 ± 0.2	1	2016-02-15	2:00 pm	2016-02-19	2:00 pm	7701824	TYLER PULS	CC	
1431	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701828	TYLER PULS	CC	
1432	0.8 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701827	TYLER PULS	CC	
1433	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701830	TYLER PULS	CC	
1434	0.6 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701835	TYLER PULS	CC	2

RADON TEST REPORT

NORTH HIGH SCHOOL
501 HOLCOMB AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1501	0.7 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701840	TYLER PULS	CC	
1502	0.8 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701842	TYLER PULS	CC	
1511	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701843	TYLER PULS	CC	
1512	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701846	TYLER PULS	CC	
1513	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701844	TYLER PULS	CC	
1513A	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701845	TYLER PULS	CC	
1514	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701847	TYLER PULS	CC	
1515	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701848	TYLER PULS	CC	
1522	< 0.3 ± 0.2	1	2016-02-15	3:00 pm	2016-02-19	2:00 pm	7701849	TYLER PULS	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

OAK PARK ELEMENTARY
3928 6TH AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
111	1.8 ±	1	2014-02-11		2014-02-14		4651691	CONSULTANT	CC	
112	2.0 ±	1	2014-02-11		2014-02-14		4651681	CONSULTANT	CC	
115	2.6 ±	1	2014-02-11		2014-02-14		4651692	CONSULTANT	CC	
128	2.3 ±	1	2014-02-11		2014-02-14		4651690	CONSULTANT	CC	
129	2.3 ±	1	2014-02-11		2014-02-14		4651689	CONSULTANT	CC	
131	2.6 ±	1	2014-02-11		2014-02-14		4651693	CONSULTANT	CC	
138	2.7 ±	1	2014-02-11		2014-02-14		4651688	CONSULTANT	CC	
Cafeteria	2.3 ±	1	2014-02-11		2014-02-14		4651686	CONSULTANT	CC	
Library	2.2 ±	1	2014-02-11		2014-02-14		4651694	CONSULTANT	CC	
Main Office	1.6 ±	1	2014-02-11		2014-02-14		4651685	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

PARK AVENUE ELEMENTARY
3141 PARK AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
101	3.1 ±	1	2013-02-11		2013-02-14		4600145	CONSULTANT	CC	
104	2.2 ±	1	2013-02-11		2013-02-14		4600137	CONSULTANT	CC	
107	2.2 ±	1	2013-02-11		2013-02-14		4600138	CONSULTANT	CC	
114	2.7 ±	1	2013-02-11		2013-02-14		4600144	CONSULTANT	CC	
Cafeteria	1.3 ±	0	2013-02-11		2013-02-14		4600131	CONSULTANT	CC	
E10	1.8 ±	1	2013-02-11		2013-02-14		4600132	CONSULTANT	CC	
E2	2.0 ±	1	2013-02-11		2013-02-14		4600139	CONSULTANT	CC	
E6	2.4 ±	1	2013-02-11		2013-02-14		4600113	CONSULTANT	CC	
Gym	1.9 ±	1	2013-02-11		2013-02-14		4600133	CONSULTANT	CC	
Office	3.2 ±	1	2013-02-11		2013-02-14		4600107	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

PERKINS ELEMENTARY
4201 COLLEGE AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
114	4.0 ±	1	2014-03-03		2014-07-25		4924361	CONSULTANT	AT	
116	6.8 ±	1	2014-03-03		2014-03-06		4651439	CONSULTANT	CC	
118	4.9 ±	1	2014-03-03		2014-07-25		4937644	CONSULTANT	AT	
122	4.8 ±	1	2014-03-03		2014-07-25		4937632	CONSULTANT	AT	
127	3.8 ±	1	2014-03-03		2014-07-25		4937614	CONSULTANT	AT	
141	6.3 ±	1	2014-03-03		2014-03-06		4651443	CONSULTANT	CC	
Gym	4.3 ±	1	2014-03-03		2014-07-25		4937570	CONSULTANT	AT	
Library	6.6 ±	1	2014-03-03		2014-03-06		4651428	CONSULTANT	CC	
Office	3.7 ±	1	2014-03-03		2014-07-25		4937654	CONSULTANT	AT	
114	6.6 ±	1	2014-02-10		2014-02-13		4651668	CONSULTANT	CC	
116	8.6 ±	1	2014-02-10		2014-02-13		4651673	CONSULTANT	CC	
118	7.3 ±	1	2014-02-10		2014-02-13		4651671	CONSULTANT	CC	
122	5.8 ±	1	2014-02-10		2014-02-13		4651666	CONSULTANT	CC	
127	5.8 ±	1	2014-02-10		2014-02-13		4651663	CONSULTANT	CC	
141	7.9 ±	1	2014-02-10		2014-02-13		4651669	CONSULTANT	CC	
Gym	6.6 ±	1	2014-02-10		2014-02-13		4651664	CONSULTANT	CC	
Gym	7.6 ±	1	2014-02-10		2014-02-13		4651662	CONSULTANT	CC	
Library	8.0 ±	1	2014-02-10		2014-02-13		4651667	CONSULTANT	CC	
Main Office	6.1 ±	1	2014-02-10		2014-02-13		4651670	CONSULTANT	CC	

RADON TEST REPORT

PERKINS ELEMENTARY
4201 COLLEGE AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

PHILLIPS ELEMENTARY
1701 LAY STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
14	9.1 ±	1	2014-02-28		2014-07-25		4924327	CONSULTANT	AT	
Gym	2.4 ±	1	2014-02-28		2014-07-25		4924357	CONSULTANT	AT	
117	3.4 ±	1	2014-01-27		2014-01-30		4738610	CONSULTANT	CC	
16	5.4 ±	1	2014-01-27		2014-01-30		4738605	CONSULTANT	CC	
20	3.2 ±	1	2014-01-27		2014-01-30		4738606	CONSULTANT	CC	
5	3.2 ±	1	2014-01-27		2014-01-30		4738599	CONSULTANT	CC	
6	3.5 ±	1	2014-01-27		2014-01-30		4738608	CONSULTANT	CC	
9	3.5 ±	1	2014-01-27		2014-01-30		4738609	CONSULTANT	CC	
Cafeteria	1.7 ±	1	2014-01-27		2014-01-30		4738604	CONSULTANT	CC	
Gym	5.5 ±	1	2014-01-27		2014-01-30		4738611	CONSULTANT	CC	
Nurse	3.6 ±	1	2014-01-27		2014-01-30		4738598	CONSULTANT	CC	
Office	2.8 ±	1	2014-01-27		2014-01-30		4738603	CONSULTANT	CC	
14	8.8 ±	1	2012-03-30		2012-04-02		4542292	CONSULTANT	CC	
14	7.4 ±	1	2012-03-07		2012-03-09		4542254	CONSULTANT	CC	
Gym SW	3.2 ±	1	2012-03-07		2012-03-09		4542258	CONSULTANT	CC	
Nurse	2.6 ±	1	2012-03-07		2012-03-09		4542257	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

PLEASANT HILL ELEMENTARY
4801 E OAKWOOD DR



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1008	2.5 ±	1	2014-02-28		2014-07-25		4923001	CONSULTANT	AT	
1050	±	1	2014-02-28				4923003	CONSULTANT	AT	2
11	2.5 ±	0	2014-02-28		2014-07-25		4924317	CONSULTANT	AT	
Office	2.5 ±	1	2014-02-28		2014-07-25		4924710	CONSULTANT	AT	
1008	4.4 ±	1	2014-01-27		2014-01-30		4738634	CONSULTANT	CC	
1048	3.1 ±	1	2014-01-27		2014-01-30		4738633	CONSULTANT	CC	
1050	5.0 ±	1	2014-01-27		2014-01-30		4738635	CONSULTANT	CC	
11	4.0 ±	0	2014-01-27		2014-01-30		4738636	CONSULTANT	CC	
13	3.9 ±	0	2014-01-27		2014-01-30		4738637	CONSULTANT	CC	
21	2.3 ±	0	2014-01-27		2014-01-30		4738631	CONSULTANT	CC	
31	1.4 ±	0	2014-01-27		2014-01-30		4738639	CONSULTANT	CC	
37	1.3 ±	0	2014-01-27		2014-01-30		4738632	CONSULTANT	CC	
Gym	2.9 ±	0	2014-01-27		2014-01-30		4738641	CONSULTANT	CC	
Office	4.0 ±	1	2014-01-27		2014-01-30		4738640	CONSULTANT	CC	
10	1.2 ±	1	2012-03-07		2012-03-09		4542261	CONSULTANT	CC	
Nurse	1.0 ±	1	2012-03-07		2012-03-09		4542259	CONSULTANT	CC	
Pre K	1.0 ±	1	2012-03-07		2012-03-09		4542260	CONSULTANT	CC	

RADON TEST REPORT

PLEASANT HILL ELEMENTARY
4801 E OAKWOOD DR



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

RIVER WOODS ELEMENTARY
2929 SE 22ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	1.1 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701463	TYLER PULS	CC	
101	1.5 ± 0.4	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701465	TYLER PULS	CC	
102	1.1 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701466	TYLER PULS	CC	
103	1 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701467	TYLER PULS	CC	
104	0.8 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701468	TYLER PULS	CC	
105	1.3 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701470	TYLER PULS	CC	
106	0.8 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701471	TYLER PULS	CC	
107	2.3 ± 0.4	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701472	TYLER PULS	CC	
107S	1.6 ± 0.4	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701478	TYLER PULS	CC	
108	0.9 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701473	TYLER PULS	CC	
109	1.3 ± 0.4	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701475	TYLER PULS	CC	
110	1.1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701479	TYLER PULS	CC	
111	1.8 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701480	TYLER PULS	CC	
112	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701481	TYLER PULS	CC	
113	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701482	TYLER PULS	CC	
114	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701483	TYLER PULS	CC	
115	2.7 ± 0.5	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701484	TYLER PULS	CC	
116	1.3 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701486	TYLER PULS	CC	
117	0.9 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701498	TYLER PULS	CC	
118	1.3 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701487	TYLER PULS	CC	
118S	1.3 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701497	TYLER PULS	CC	
118S	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701488	TYLER PULS	CC	
119	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701494	TYLER PULS	CC	
119A	0.9 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	11:00 am	7701495	TYLER PULS	CC	
119C	0.6 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	11:00 am	7701496	TYLER PULS	CC	
120	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701489	TYLER PULS	CC	
121	<0.3 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701501	TYLER PULS	CC	
121A	1 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701502	TYLER PULS	CC	
121C	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701492	TYLER PULS	CC	
121D	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701504	TYLER PULS	CC	
122	1.1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701511	TYLER PULS	CC	
122A	1 ± 0.4	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701512	TYLER PULS	CC	

RADON TEST REPORT

RIVER WOODS ELEMENTARY
2929 SE 22ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
122B	0.6 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	11:00 am	7701490	TYLER PULS	CC	
123	0.7 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701491	TYLER PULS	CC	
124	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701509	TYLER PULS	CC	
125	1.4 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701508	TYLER PULS	CC	
126	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701507	TYLER PULS	CC	
127	1.4 ± 0.4	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701505	TYLER PULS	CC	
128	0.8 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701503	TYLER PULS	CC	
129	0.6 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701513	TYLER PULS	CC	
129A	<0.3 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701514	TYLER PULS	CC	
129B	0.9 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701516	TYLER PULS	CC	
129C	0.6 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701515	TYLER PULS	CC	
130	0.8 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701519	TYLER PULS	CC	
131	0.8 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	10:00 am	7701517	TYLER PULS	CC	
132	0.6 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701523	TYLER PULS	CC	
133	0.8 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701525	TYLER PULS	CC	
133A	<0.3 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701527	TYLER PULS	CC	
134S	0.8 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701526	TYLER PULS	CC	
135	0.6 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701522	TYLER PULS	CC	
136	0.8 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701520	TYLER PULS	CC	
136A	1 ± 0.3	1	2016-01-19	11:00 am	2016-01-22	11:00 am	7701521	TYLER PULS	CC	
137	1 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	10:00 am	7701500	TYLER PULS	CC	
137A	0.6 ± 0.3	1	2016-01-19	10:00 am	2016-01-22	11:00 am	7701499	TYLER PULS	CC	
92	1 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701464	TYLER PULS	CC	
97	1.3 ± 0.4	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701460	TYLER PULS	CC	
98	0.6 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701461	TYLER PULS	CC	
99	1.1 ± 0.3	1	2016-01-19	9:00 am	2016-01-22	10:00 am	7701462	TYLER PULS	CC	
124	<0.3 ±	1	2012-03-07		2013-03-09		4542268	CONSULTANT	CC	
Gym NE	<0.3 ±	1	2012-03-07		2013-03-09		4542266	CONSULTANT	CC	
Gym SW	<0.3 ±	1	2012-03-07		2013-03-09		4542267	CONSULTANT	CC	
Nurse	<0.3 ±	1	2012-03-07		2013-03-09		4542265	CONSULTANT	CC	

RADON TEST REPORT

RIVER WOODS ELEMENTARY
2929 SE 22ND STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

ROOSEVELT HIGH SCHOOL
4419 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1070	4.3 ±	1	2013-03-22		2013-06-27		4894880	CONSULTANT	AT	
1410	3.3 ±	1	2013-03-22		2013-06-27		4894878	CONSULTANT	AT	
1060	3.8 ±	1	2013-02-25		2013-02-28		4600249	CONSULTANT	CC	
1070	4.0 ±	1	2013-02-25		2013-02-28		4600236	CONSULTANT	CC	
1110	2.2 ±	1	2013-02-25		2013-02-28		4600248	CONSULTANT	CC	
1130	1.6 ±	1	2013-02-25		2013-02-28		4600247	CONSULTANT	CC	
1250	3.4 ±	1	2013-02-25		2013-02-28		4600246	CONSULTANT	CC	
1290	1.8 ±	1	2013-02-25		2013-02-28		4600245	CONSULTANT	CC	
1340	2.1 ±	1	2013-02-25		2013-02-28		4600243	CONSULTANT	CC	
1410	5.7 ±	1	2013-02-25		2013-02-28		4600250	CONSULTANT	CC	
1470	<0.3 ±	1	2013-02-25		2013-02-28		4600244	CONSULTANT	CC	
1510	1.1 ±	1	2013-02-25		2013-02-28		4600235	CONSULTANT	CC	
1600	1.7 ±	1	2013-02-25		2013-02-28		4600227	CONSULTANT	CC	
1670	1.6 ±	1	2013-02-25		2013-02-28		4600253	CONSULTANT	CC	
1780	2.5 ±	1	2013-02-25		2013-02-28		4600232	CONSULTANT	CC	
1800	2.7 ±	1	2013-02-25		2013-02-28		4600255	CONSULTANT	CC	
1830	2.7 ±	1	2013-02-25		2013-02-28		4600229	CONSULTANT	CC	
1840	2.6 ±	1	2013-02-25		2013-02-28		4600256	CONSULTANT	CC	
1860	2.2 ±	1	2013-02-25		2013-02-28		4600234	CONSULTANT	CC	
1870	2.7 ±	1	2013-02-25		2013-02-28		4600240	CONSULTANT	CC	
1880	2.3 ±	1	2013-02-25		2013-02-28		4600231	CONSULTANT	CC	
2250	2.2 ±	2	2013-02-25		2013-02-28		4600228	CONSULTANT	CC	
Cafeteria	2.1 ±	1	2013-02-25		2013-02-28		4600233	CONSULTANT	CC	
Office	3.3 ±	1	2013-02-25		2013-02-28		4600239	CONSULTANT	CC	

RADON TEST REPORT

ROOSEVELT HIGH SCHOOL
4419 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

SAMUELSON ELEMENTARY
3929 BEL AIRE RD.



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	1.1 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701177	TYLER PULS	CC	
101	1.1 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701174	TYLER PULS	CC	
103	0.9 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701181	TYLER PULS	CC	
105	1.2 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701180	TYLER PULS	CC	
106	1.1 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701179	TYLER PULS	CC	
107	1.9 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701178	TYLER PULS	CC	
108	1.2 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701176	TYLER PULS	CC	
109	1.4 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701175	TYLER PULS	CC	
110	0.8 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701173	TYLER PULS	CC	
111	0.8 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701170	TYLER PULS	CC	
112	1.2 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701171	TYLER PULS	CC	
113	0.8 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701169	TYLER PULS	CC	
114	0.9 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701165	TYLER PULS	CC	
114A	0.9 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701166	TYLER PULS	CC	
115	0.6 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701164	TYLER PULS	CC	
116	0.8 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701163	TYLER PULS	CC	
117	1 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701205	TYLER PULS	CC	
117A	1.1 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701206	TYLER PULS	CC	
118	< 0.3 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701162	TYLER PULS	CC	
119	0.5 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701161	TYLER PULS	CC	
121	0.6 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701160	TYLER PULS	CC	
122	0.6 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701159	TYLER PULS	CC	
123	< 0.3 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701158	TYLER PULS	CC	
124	1.4 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701207	TYLER PULS	CC	
124A	1.5 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701208	TYLER PULS	CC	
125	1.3 ± 0.3	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701209	TYLER PULS	CC	
127	< 0.3 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701202	TYLER PULS	CC	
128	< 0.3 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701157	TYLER PULS	CC	
130	0.6 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701201	TYLER PULS	CC	
131	0.6 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701200	TYLER PULS	CC	
132	0.6 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701198	TYLER PULS	CC	
133	< 0.3 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701197	TYLER PULS	CC	

RADON TEST REPORT

SAMUELSON ELEMENTARY
3929 BEL AIRE RD.



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
134	1.1 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701195	TYLER PULS	CC	
135	0.5 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701194	TYLER PULS	CC	
136	0.8 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701193	TYLER PULS	CC	
137	0.7 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701192	TYLER PULS	CC	
138	1.2 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701191	TYLER PULS	CC	
140	1 ± 0.2	1	2015-11-30	11:00 am	2015-12-04	11:00 am	7701167	TYLER PULS	CC	
141	1.3 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701190	TYLER PULS	CC	
142	1 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701188	TYLER PULS	CC	
143	1 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701187	TYLER PULS	CC	
144	0.6 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701186	TYLER PULS	CC	
145	0.9 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701185	TYLER PULS	CC	
146	< 0.3 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701184	TYLER PULS	CC	
147	0.9 ± 0.2	1	2015-11-30	12:00 pm	2015-12-04	12:00 pm	7701183	TYLER PULS	CC	
301	0.7 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701199	TYLER PULS	CC	
303	0.6 ± 0.2	1	2015-11-30	1:00 pm	2015-12-04	1:00 pm	7701204	TYLER PULS	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

1 = Closed building conditions not maintained throughout testing duration.

2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

SMOUSE OPPORTUNITY SCHOOL
2820 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
105	< 0.3 \pm	1	2014-03-10		2014-03-13		4738555	CONSULTANT	CC	
117	3.1 \pm	1	2014-03-10		2014-03-13		4738552	CONSULTANT	CC	
121	< 0.3 \pm	1	2014-03-10		2014-03-13		4738553	CONSULTANT	CC	
123	< 0.3 \pm	1	2014-03-10		2014-03-13		4738558	CONSULTANT	CC	
200	< 0.3 \pm	2	2014-03-10		2014-03-13		4738550	CONSULTANT	CC	
202	< 0.3 \pm	2	2014-03-10		2014-03-13		4651497	CONSULTANT	CC	
206A	0.5 \pm	2	2014-03-10		2014-03-13		4738551	CONSULTANT	CC	
Cafeteria	0.9 \pm	1	2014-03-10		2014-03-13		4738557	CONSULTANT	CC	
Main Office	0.8 \pm	2	2014-03-10		2014-03-13		4651498	CONSULTANT	CC	
Staff Loung	0.5 \pm	1	2014-03-10		2014-03-13		4738554	CONSULTANT	CC	
115	<0.3 \pm	1	2011-11-07		2011-11-10		4448641	CONSULTANT	CC	
200	1.2 \pm	1	2011-11-07		2011-11-10		4542203	CONSULTANT	AT	
202	1.3 \pm	1	2011-11-07		2011-11-10		4448644	CONSULTANT	CC	
204	0.8 \pm	1	2011-11-07		2011-11-10		4448639	CONSULTANT	CC	
206	1.7 \pm	1	2011-11-07		2011-11-10		4448642	CONSULTANT	CC	
Atrium	1.2 \pm	1	2011-11-07		2011-11-10		4542216	CONSULTANT	CC	
Gym	1.0 \pm	2	2011-11-07		2011-11-10		4542229	CONSULTANT	CC	
Gym	1.1 \pm	2	2011-11-07		2011-11-10		4542228	CONSULTANT	CC	
Nurse	1.4 \pm	2	2011-11-07		2011-11-10		4542221	CONSULTANT	CC	

RADON TEST REPORT

SMOUSE OPPORTUNITY SCHOOL
2820 CENTER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

SOUTH UNION ELEMENTARY
4201 S UNION STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
208	4.7 ±	1	2015-01-23		2015-05-11		4937613	CONSULTANT	AT	
111	1.5 ±	1	2014-12-10		2014-12-12		7014767	CONSULTANT	CC	
112	1.7 ±	1	2014-12-10		2014-12-12		7014762	CONSULTANT	CC	
113	1.3 ±	1	2014-12-10		2014-12-12		7014765	CONSULTANT	CC	
114	1.3 ±	1	2014-12-10		2014-12-12		7014757	CONSULTANT	CC	
115	< 0.3 ±	1	2014-12-10		2014-12-12		7014766	CONSULTANT	CC	
115	< 0.3 ±	1	2014-12-10		2014-12-12		7014761	CONSULTANT	CC	
208	4.2 ±	2	2014-12-10		2014-12-12		7014768	CONSULTANT	CC	
213	3.2 ±	2	2014-12-10		2014-12-12		7014756	CONSULTANT	CC	
225	3.2 ±	2	2014-12-10		2014-12-12		7014760	CONSULTANT	CC	
230	1.8 ±	2	2014-12-10		2014-12-12		7014764	CONSULTANT	CC	
235	1.9 ±	2	2014-12-10		2014-12-12		7014758	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

STOWE ELEMENTARY
1411 E 33RD STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
117	0.8 ±	1	2013-02-12		2013-01-15		4600141	CONSULTANT	CC	
119	0.9 ±	1	2013-02-12		2013-01-15		4600109	CONSULTANT	CC	
121	0.8 ±	1	2013-02-12		2013-01-15		4600153	CONSULTANT	CC	
123	1.3 ±	1	2013-02-12		2013-01-15		4600142	CONSULTANT	CC	
128	1.2 ±	1	2013-02-12		2013-01-15		4600154	CONSULTANT	CC	
132	1.6 ±	1	2013-02-12		2013-01-15		4600148	CONSULTANT	CC	
136	1.4 ±	1	2013-02-12		2013-01-15		4600152	CONSULTANT	CC	
Cafeteria	1.2 ±	1	2013-02-12		2013-01-15		4600143	CONSULTANT	CC	
Gym	1.1 ±	1	2013-02-12		2013-01-15		4600147	CONSULTANT	CC	
Library	1.7 ±	1	2013-02-12		2013-01-15		4600136	CONSULTANT	CC	
Office/Rec	0.7 ±	1	2013-02-12		2013-01-15		4600111	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

STUDEBAKER ELEMENTARY
300 E COUNTY LINE RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
1120	4.3 ±	1	2014-03-03		2014-07-25		4937577	CONSULTANT	AT	
1165	2.0 ±	1	2014-03-03		2014-03-06		4651426	CONSULTANT	CC	
1170	2.1 ±	1	2014-03-03		2014-07-25		4937670	CONSULTANT	AT	
1210	2.8 ±	1	2014-03-03		2014-07-25		4937572	CONSULTANT	AT	
1230	4.0 ±	1	2014-03-03		2014-03-06		4651434	CONSULTANT	CC	
1245	4.5 ±	1	2014-03-03		2014-03-06		4651440	CONSULTANT	CC	
1260	5.9 ±	1	2014-03-03		2014-07-25		4924322	CONSULTANT	AT	
Gym	2.8 ±	1	2014-03-03		2014-07-25		4924346	CONSULTANT	AT	
1115	2.1 ±	1	2014-02-03		2014-02-06		4651337	CONSULTANT	CC	
1120	7.1 ±	1	2014-02-03		2014-02-06		4651333	CONSULTANT	CC	
1170	4.9 ±	1	2014-02-03		2014-02-06		4651339	CONSULTANT	CC	
1210	6.8 ±	1	2014-02-03		2014-02-06		4651336	CONSULTANT	CC	
1230	8.0 ±	1	2014-02-03		2014-02-06		4651334	CONSULTANT	CC	
1245	8.4 ±	1	2014-02-03		2014-02-06		4651335	CONSULTANT	CC	
Gym	4.9 ±	1	2014-02-03		2014-02-06		4651329	CONSULTANT	CC	
Main Office	3.4 ±	1	2014-02-03		2014-02-06		4651330	CONSULTANT	CC	
Music	6.5 ±	1	2014-02-03		2014-02-06		4651331	CONSULTANT	CC	
104	3.9 ±	1	2011-11-07		2011-11-10		4542204	CONSULTANT	CC	
Gym	0.9 ±	1	2011-11-07		2011-11-10		4542201	CONSULTANT	CC	
Gym	0.7 ±	1	2011-11-07		2011-11-10		4542214	CONSULTANT	CC	

RADON TEST REPORT

STUDEBAKER ELEMENTARY
300 E COUNTY LINE RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	----------------	-------	------------	------------	----------	----------	------------	------------------------	-------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

RUBY VAN METER SCHOOL
710 28TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	0.8 ±	1	2013-03-21		2013-06-27		4894900	CONSULTANT	CC	
101	0.6 ±	1	2013-03-21		2013-06-27		4894970	CONSULTANT	AT	
100	3.8 ±	1	2013-02-25		2013-02-28		4600257	CONSULTANT	CC	
101	4.9 ±	1	2013-02-25		2013-02-28		4600267	CONSULTANT	CC	
103	1.1 ±	0	2013-02-25		2013-02-28		4600262	CONSULTANT	CC	
104	1.2 ±	0	2013-02-25		2013-02-28		4600268	CONSULTANT	CC	
106	1.0 ±	0	2013-02-25		2013-02-28		4600260	CONSULTANT	CC	
111	0.9 ±	0	2013-02-25		2013-02-28		4600258	CONSULTANT	CC	
201D	1.2 ±	1	2013-02-25		2013-02-28		4600264	CONSULTANT	CC	
201F	1.3 ±	1	2013-02-25		2013-02-28		4600238	CONSULTANT	CC	
202	1.1 ±	1	2013-02-25		2013-02-28		4600261	CONSULTANT	CC	
203F	0.9 ±	1	2013-02-25		2013-02-28		4600263	CONSULTANT	CC	
206	0.6 ±	1	2013-02-25		2013-02-28		4600237	CONSULTANT	CC	
207	0.7 ±	1	2013-02-25		2013-02-28		4600251	CONSULTANT	CC	
213	0.7 ±	1	2013-02-25		2013-02-28		4600254	CONSULTANT	CC	
217	1.3 ±	1	2013-02-25		2013-02-28		4600259	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WALKER STREET
1421 WALKER STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
103	2.1 ±	1	2014-01-28		2014-01-31		4651574	CONSULTANT	CC	
105	1.6 ±	1	2014-01-28		2014-01-31		4651573	CONSULTANT	CC	
112	2.0 ±	1	2014-01-28		2014-01-31		4651575	CONSULTANT	CC	
113	1.4 ±	1	2014-01-28		2014-01-31		4651572	CONSULTANT	CC	
119	2.1 ±	1	2014-01-28		2014-01-31		4651571	CONSULTANT	CC	
120	2.0 ±	1	2014-01-28		2014-01-31		4651578	CONSULTANT	CC	
123	2.0 ±	1	2014-01-28		2014-01-31		4651563	CONSULTANT	CC	
Cafeteria	1.5 ±	1	2014-01-28		2014-01-31		4651567	CONSULTANT	CC	
Main Office	1.6 ±	1	2014-01-28		2014-01-31		4651566	CONSULTANT	CC	
Nurse	1.7 ±	1	2014-01-28		2014-01-31		4651577	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WALNUT STREET
901 WALNUT STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
204	<0.3 ±	2	2014-03-10		2014-03-13		4651467	CONSULTANT	CC	
205	<0.3 ±	2	2014-03-10		2014-03-13		4651470	CONSULTANT	CC	
207	<0.3 ±	2	2014-03-10		2014-03-13		4651469	CONSULTANT	CC	
213	<0.3 ±	2	2014-03-10		2014-03-13		4651471	CONSULTANT	CC	
215	<0.3 ±	2	2014-03-10		2014-03-13		4651468	CONSULTANT	CC	
Cafeteria	<0.3 ±	2	2014-03-10		2014-03-13		4651453	CONSULTANT	CC	
Cafeteria	<0.3 ±	2	2014-03-10		2014-03-13		4651435	CONSULTANT	CC	
Gym	<0.3 ±	2	2014-03-10		2014-03-13		4651466	CONSULTANT	CC	
Gym	<0.3 ±	2	2014-03-10		2014-03-13		4651465	CONSULTANT	CC	
Reception	<0.3 ±	1	2014-03-10		2014-03-13		4651472	CONSULTANT	CC	
316	<0.3 ±	3	2011-11-07		2011-11-10		4542209	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WEEKS MIDDLE SCHOOL
901 E PARK AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	2.3 ±	1	2014-02-03		2014-02-06		4651309	CONSULTANT	CC	
101	2.3 ±	1	2014-02-03		2014-02-06		4651306	CONSULTANT	CC	
102	3.2 ±	1	2014-02-03		2014-02-06		4651313	CONSULTANT	CC	
1050/200	2.3 ±	2	2014-02-03		2014-02-06		4651304	CONSULTANT	CC	
1054/212	3.3 ±	2	2014-02-03		2014-02-06		4651314	CONSULTANT	CC	
133	3.0 ±	1	2014-02-03		2014-02-06		4651310	CONSULTANT	CC	
142	3.3 ±	1	2014-02-03		2014-02-06		4651305	CONSULTANT	CC	
143	3.0 ±	1	2014-02-03		2014-02-06		4651316	CONSULTANT	CC	
153	1.1 ±	1	2014-02-03		2014-02-06		4651312	CONSULTANT	CC	
156	1.6 ±	1	2014-02-03		2014-02-06		4651308	CONSULTANT	CC	
185	1.2 ±	1	2014-02-03		2014-02-06		4651302	CONSULTANT	CC	
2	<0.3 ±	1	2014-02-03		2014-02-06		4651303	CONSULTANT	CC	
3	<0.3 ±	1	2014-02-03		2014-02-06		4651315	CONSULTANT	CC	
9	0.5 ±	1	2014-02-03		2014-02-06		4651317	CONSULTANT	CC	
Gym	1.6 ±	1	2014-02-03		2014-02-06		4651301	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

1 = Closed building conditions not maintained throughout testing duration.

2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WILLARD ELEMENTARY
2941 DEAN AVENUE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
104	±	1	2014-02-28				4924376	CONSULTANT	AT	2
106	4.5 ±	1	2014-02-28		2014-07-25		4924358	CONSULTANT	AT	
107	4.6 ±	1	2014-02-28		2014-07-25		4924338	CONSULTANT	AT	
108	3.7 ±	1	2014-02-28		2014-07-25		4924364	CONSULTANT	AT	
109	4.6 ±	1	2014-02-28		2014-07-25		4924334	CONSULTANT	AT	
Gym	±	1	2014-02-28				4924332	CONSULTANT	AT	2
Office	4.3 ±	1	2014-02-28		2014-07-25		4924316	CONSULTANT	AT	
101C	3.5 ±	1	2014-01-27		2014-01-30		4738628	CONSULTANT	CC	
103	3.0 ±	1	2014-01-27		2014-01-30		4738645	CONSULTANT	CC	
104	4.2 ±	1	2014-01-27		2014-01-30		4738646	CONSULTANT	CC	
106	4.3 ±	1	2014-01-27		2014-01-30		4738642	CONSULTANT	CC	
107	4.4 ±	1	2014-01-27		2014-01-30		4738644	CONSULTANT	CC	
108	4.4 ±	1	2014-01-27		2014-01-30		4738647	CONSULTANT	CC	
109	4.0 ±	1	2014-01-27		2014-01-30		4738615	CONSULTANT	CC	
Cafeteria	3.2 ±	1	2014-01-27		2014-01-30		4725376	CONSULTANT	CC	
Gym	3.8 ±	1	2014-01-27		2014-01-30		4738618	CONSULTANT	CC	
Office	5.1 ±	1	2014-01-27		2014-01-30		4738623	CONSULTANT	CC	
100	3.0 ±	1	2012-03-07		2012-03-09		4542264	CONSULTANT	CC	
103	2.9 ±	1	2012-03-07		2012-03-09		4542262	CONSULTANT	CC	
Gym NE	2.9 ±	1	2012-03-07		2012-03-09		4542263	CONSULTANT	CC	
Gym SE	2.7 ±	1	2012-03-07		2012-03-09		4542255	CONSULTANT	CC	

RADON TEST REPORT

WILLARD ELEMENTARY
2941 DEAN AVENUE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WINDSOR ELEMENTARY
5912 UNIVERSITY AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
107	5.2 ±	1	2013-03-22		2013-06-27		4894946	CONSULTANT	AT	
115	4.7 ±	1	2013-03-22		2013-06-27		4894890	CONSULTANT	AT	
116	4.6 ±	1	2013-03-22		2013-06-27		4894939	CONSULTANT	AT	
119	4.3 ±	1	2013-03-22		2013-06-27		4894936	CONSULTANT	AT	
120	4.6 ±	1	2013-03-22		2013-06-27		4894929	CONSULTANT	AT	
207	3.5 ±	2	2013-03-22		2013-06-27		4894930	CONSULTANT	AT	
209	3.5 ±	2	2013-03-22		2013-06-27		4894928	CONSULTANT	AT	
210	2.7 ±	2	2013-03-22		2013-06-27		4894910	CONSULTANT	AT	
106	3.3 ±	1	2013-02-19		2013-02-21		4600210	CONSULTANT	CC	
107	5.7 ±	1	2013-02-19		2013-02-21		4600220	CONSULTANT	CC	
108	3.2 ±	1	2013-02-19		2013-02-21		4600202	CONSULTANT	CC	
110	3.5 ±	1	2013-02-19		2013-02-21		4600197	CONSULTANT	CC	
115	7.0 ±	1	2013-02-19		2013-02-21		4600219	CONSULTANT	CC	
116	5.6 ±	1	2013-02-19		2013-02-21		4600221	CONSULTANT	CC	
119	5.1 ±	1	2013-02-19		2013-02-21		4600208	CONSULTANT	CC	
120	6.8 ±	1	2013-02-19		2013-02-21		4600215	CONSULTANT	CC	
207	6.9 ±	2	2013-02-19		2013-02-21		4600216	CONSULTANT	CC	
209	6.7 ±	2	2013-02-19		2013-02-21		4600209	CONSULTANT	CC	
210	5.1 ±	2	2013-02-19		2013-02-21		4600217	CONSULTANT	CC	
Gym	2.0 ±	1	2013-02-19		2013-02-21		4600207	CONSULTANT	CC	
Office	3.7 ±	1	2013-02-19		2013-02-21		4600225	CONSULTANT	CC	

RADON TEST REPORT

WINDSOR ELEMENTARY
5912 UNIVERSITY AVE



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
------	-------------------	-------	------------	------------	----------	----------	------------	---------------------------	----------------	-------

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WOODLAWN EDUCATION CENTER
4000 LOWER BEAVER RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
100	1.7 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701979	TYLER PULS	CC	
100B	1.5 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701980	TYLER PULS	CC	
102	2 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701978	TYLER PULS	CC	
104	2.3 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701977	TYLER PULS	CC	
105	1.3 ± 0.3	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701973	TYLER PULS	CC	
105B	1.4 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701974	TYLER PULS	CC	
106	1.8 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701972	TYLER PULS	CC	
107	1.2 ± 0.3	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701968	TYLER PULS	CC	
107A	1.4 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701975	TYLER PULS	CC	
107B	1.5 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701976	TYLER PULS	CC	
108	1.7 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701970	TYLER PULS	CC	
109	2.4 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701969	TYLER PULS	CC	
110	1.6 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701967	TYLER PULS	CC	
111	1.9 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701966	TYLER PULS	CC	
112	2.1 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701965	TYLER PULS	CC	
113	1.9 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701964	TYLER PULS	CC	
114	2.2 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701963	TYLER PULS	CC	
115	2.7 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701962	TYLER PULS	CC	
116	3.5 ± 0.5	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701961	TYLER PULS	CC	
117	3.2 ± 0.5	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701958	TYLER PULS	CC	
117A	3 ± 0.5	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701959	TYLER PULS	CC	
117B	2.8 ± 0.5	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701960	TYLER PULS	CC	
118	2.7 ± 0.5	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701955	TYLER PULS	CC	
119	2.4 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701956	TYLER PULS	CC	
120	2.1 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701952	TYLER PULS	CC	
120C	2.2 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701954	TYLER PULS	CC	
121	1.9 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701953	TYLER PULS	CC	
122	2 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701949	TYLER PULS	CC	
123	2.3 ± 0.4	1	2016-03-22	11:00 am	2016-03-25	11:00 am	7701950	TYLER PULS	CC	
90	1.4 ± 0.3	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701985	TYLER PULS	CC	
92	1.8 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701991	TYLER PULS	CC	
93	1.3 ± 0.3	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701990	TYLER PULS	CC	

RADON TEST REPORT

WOODLAWN EDUCATION CENTER
4000 LOWER BEAVER RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
94	1.4 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701988	TYLER PULS	CC	
95	1.1 ± 0.3	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701989	TYLER PULS	CC	
96	1.3 ± 0.3	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701983	TYLER PULS	CC	
96A	1.5 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701984	TYLER PULS	CC	
97	1.7 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701986	TYLER PULS	CC	
98	1.8 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701981	TYLER PULS	CC	
99	2.2 ± 0.4	1	2016-03-22	12:00 pm	2016-03-25	11:00 am	7701982	TYLER PULS	CC	
104	2 ±	1	2014-04-07		2014-07-25		4937597	CONSULTANT	AT	
104	4.1 ±	1	2014-03-24		2012-03-27		4651201	CONSULTANT	CC	
111	2 ±	1	2014-03-24		2012-03-27		4651225	CONSULTANT	CC	
112	1.7 ±	1	2014-03-24		2012-03-27		4651227	CONSULTANT	CC	
113	2.5 ±	1	2014-03-24		2012-03-27		4651223	CONSULTANT	CC	
114	1.9 ±	1	2014-03-24		2012-03-27		4651226	CONSULTANT	CC	
115	2.8 ±	1	2014-03-24		2012-03-27		4738589	CONSULTANT	CC	
116	2.9 ±	1	2014-03-24		2012-03-27		4651222	CONSULTANT	CC	
118	1.8 ±	1	2014-03-24		2012-03-27		4651205	CONSULTANT	CC	
120	2.1 ±	1	2014-03-24		2012-03-27		4651206	CONSULTANT	CC	
121	1.6 ±	1	2014-03-24		2012-03-27		4651224	CONSULTANT	CC	
122	1.7 ±	1	2014-03-24		2012-03-27		4651221	CONSULTANT	CC	
123	1.7 ±	1	2014-03-24		2012-03-27		4738593	CONSULTANT	CC	
93	1.2 ±	1	2014-03-24		2012-03-27		4738590	CONSULTANT	CC	
96	2.5 ±	1	2014-03-24		2012-03-27		4651212	CONSULTANT	CC	
118	<0.3 ±	1	2012-03-30		2012-04-03		4542293	CONSULTANT	CC	
120	<0.3 ±	1	2012-03-30		2012-04-03		4542291	CONSULTANT	CC	
112	<0.3 ±	1	2012-03-07		2012-03-09		4542251	CONSULTANT	CC	
118	5 ±	1	2011-11-28		2012-03-05		4837116	CONSULTANT	AT	
120	5 ±	1	2011-11-28		2012-03-05		4837122	CONSULTANT	AT	
114	2.7 ±	1	2011-11-07		2011-11-10		4448618	CONSULTANT	CC	
116	2.6 ±	1	2011-11-07		2011-11-10		4448620	CONSULTANT	CC	
118	4.8 ±	1	2011-11-07		2011-11-10		4448622	CONSULTANT	CC	
120	5.5 ±	1	2011-11-07		2011-11-10		4448621	CONSULTANT	CC	
121	2.2 ±	1	2011-11-07		2011-11-10		4448615	CONSULTANT	CC	

RADON TEST REPORT

WOODLAWN EDUCATION CENTER
4000 LOWER BEAVER RD



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
122	2.9 ±	1	2011-11-07		2011-11-10		4448617	CONSULTANT	CC	
123	3.1 ±	1	2011-11-07		2011-11-10		4448610	CONSULTANT	CC	
Gym	1.6 ±	1	2011-11-07		2011-11-10		4448613	CONSULTANT	CC	
Nurse	2.7 ±	1	2011-11-07		2011-11-10		4448616	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested

RADON TEST REPORT

WRIGHT ELEMENTARY
5001 SW 14TH STREET



Room	Result (pCi/L)	Floor	Start Date	Start Time	End Date	End Time	Kit Number	Measurement Specialist	Sample Type	Notes
115	4.1 ±	1	2014-03-05		2014-07-25		4937671	CONSULTANT	AT	
126	4.0 ±	1	2014-03-05		2014-07-25		4937656	CONSULTANT	AT	
Library	4.4 ±	1	2014-03-05		2014-07-25		4937579	CONSULTANT	AT	
Main Office	3.4 ±	1	2014-03-05		2014-07-25		4937608	CONSULTANT	AT	
114	2.4 ±	1	2014-02-03		2014-02-06		4651353	CONSULTANT	CC	
115	4.1 ±	1	2014-02-03		2014-02-06		4651354	CONSULTANT	CC	
122	1.4 ±	1	2014-02-03		2014-02-06		4651356	CONSULTANT	CC	
125	0.9 ±	1	2014-02-03		2014-02-06		4651359	CONSULTANT	CC	
126	4.9 ±	1	2014-02-03		2014-02-06		4651361	CONSULTANT	CC	
132	0.9 ±	1	2014-02-03		2014-02-06		4651357	CONSULTANT	CC	
135	1.5 ±	1	2014-02-03		2014-02-06		4651360	CONSULTANT	CC	
136	2.4 ±	1	2014-02-03		2014-02-06		4651358	CONSULTANT	CC	
Library	5.7 ±	1	2014-02-03		2014-02-06		4651355	CONSULTANT	CC	
Main Office	4.1 ±	1	2014-02-03		2014-02-06		4651352	CONSULTANT	CC	

CC = Activated Charcoal AT = Alpha Track CRM = Continuous Radon Monitor (Average)

Notes:

- 1 = Closed building conditions not maintained throughout testing duration.
- 2 = Device missing, damaged, or tampered with during testing.

Activated charcoal test kits analyzed by Air Chek, Inc. Alpha track devices analyzed by Radon Safety Services, Inc. or Landauer, Inc. CRM measurements collected with a Femto-TECH CRM 510LP/CO.

The Iowa Department of Public Health and the Environmental Protection Agency have established an action level of 4.0 pCi/L. Radon test results are representative of the time period sampled. Test results are evaluated and acted upon based on the DMPS Radon Action Plan.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations due to changes in the weather and operation of the facility as well as possible interference with the necessary test conditions that may or may not influence the results.

It is recommended that the facility be retested in each of the following cases whether or not the building has been mitigated:

- Five years since the previous test
- An alteration is made that could change the ventilation pattern
- Major cracks or penetrations occur in the foundation walls or slab
- Changes are made or happen to an installed mitigation system
- Occupation of a ground contact area that was not previously tested